



DueList Report

FALCON 7X

S/N 107 N542GP

OWNER: CLAY LACY AVIATION, INC.
ADDRESS: 7435 VALJEAN AVENUE
VAN NUYS CA 91406
OFFICE: 818-947-5407
FAX: 818-947-5470

OPERATOR: CLAY LACY AVIATION, INC.
ADDRESS: 7435 VALJEAN AVENUE
VAN NUYS 91406
OFFICE: 818-989-2900
FAX:

OPERATOR: DASSAULT FALCON CARE
ADDRESS: TETERBORO AIRPORT
SOUTH HACKENSACK NJ 07606
OFFICE: 201-541-4759
FAX: 201-541-4762

CAMO: THURSTON AVIATION LTD
ADDRESS: HANGAR 427 BUSINESS PARK WEST
CHRISTCHURCH DORSET BH23 6EA
OFFICE: 07415984631
FAX:

ANALYST: EMILY GOMES
EMAIL: EGOMES@CAMPSYSTEMS.COM

1-631-619-4525 (DIRECT)
+1-631-588-3200 (MAIN)
WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)
631-980-4222 (FAX)

PROJECTED: 24 MOS. to 08-MAY-2026

AIRCRAFT SERIAL/REGNO: 107/N542GP MODEL: FALCON 7X MANUFACTURER: DASSAULT AVIATION S.A.

CERTIFICATION DATE: 10-FEB-2011

LAST ACTUALS:

PROJECTED:

2752.5 A/C HRS as of 23-APR-2024
1215 AFL as of 23-APR-2024
2463 APH as of 10-APR-2024
3280 APS as of 10-APR-2024

3152.50
1515
2663
3680

APU SERIAL/PART: P-171/3800788-1 MODEL: GTCP36-150(FN) MANUFACTURER: HONEYWELL

INSTALLED ON: 23-OCT-2009

LAST ACTUALS:

PROJECTED:

19.83 APU HRS 0 A/C HRS
50 APUS

2463 APU HRS as of 10-APR-2024
3280 APUS as of 10-APR-2024

2663
3680

ENGINE NO. 1 SERIAL/PART: PCE-CH0341/30P0100-01 MODEL: PW307A MANUFACTURER: PRATT & WHITNEY CANADA CORP.

INSTALLED ON: 22-JUL-2014

LAST ACTUALS:

PROJECTED:

599.25 ENG. HRS 690.5 A/C HRS
227 ENC

2659.9 ENG. HRS as of 23-APR-2024
1168 ENC as of 23-APR-2024

3059.90
1468

ENGINE NO. 2 SERIAL/PART: PCE-CH0339/30P0100-01 MODEL: PW307A MANUFACTURER: PRATT & WHITNEY CANADA CORP.

INSTALLED ON: 22-JUL-2014

LAST ACTUALS:

PROJECTED:

645.5 ENG. HRS 690.5 A/C HRS
244 ENC

2708.8 ENG. HRS as of 23-APR-2024
1187 ENC as of 23-APR-2024

3108.80
1487

ENGINE NO. 3 SERIAL/PART: PCE-CH0342/30P0100-01 MODEL: PW307A MANUFACTURER: PRATT & WHITNEY CANADA CORP.

INSTALLED ON: 22-JUL-2014

LAST ACTUALS:

PROJECTED:

645.5 ENG. HRS 690.5 A/C HRS
244 ENC

2708.8 ENG. HRS as of 23-APR-2024
1187 ENC as of 23-APR-2024

3108.80
1487



Due List Report

Model: FALCON 7X Serial: 107 RegNo: N542GP HRS: 2752.5 AFL: 1215 As Of: 23-Apr-2024 Operator: CLAY LACY AVIATION, INC.

Report Date: 08-May-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est. Due
28-30-00-680-804-01		DRAINING WATER FROM THE FUEL TANKS						Service ATA:28
	DAYS	7 (+5)		10-Apr-24	RTS-OVD			
	HRS			2744.2				
	AFL			1212				
		REF: AMM 28-30-00-680-804					WO#: POOXC24-00110.1, POOXC24-00291.1	
45-90-00-860-801-01 ^S		PERIODIC DATABASE LOADING (BLUE DISK)						Service ATA:45
	DAYS			10-Apr-24	01-May-24 (M)		OVD	
		REF: AMM 45-90-00-860-801						
05-08-00-200-800-01		12M/800FH INSPECTION						Package ATA:05
	MOS	12 (+1m)	Adj:-52d	01-Jun-23	10-Apr-24	10-May-24	TOL (+2 d)	08-May-2024(3)
	HRS	800 (+40)		2501.6	3301.6	3341.6	549.1 (+40)	
	AFL			1079				
		REF: MPD 05-10-00						
72-00-20-280-801-01		NO. 2 ENGINE - INSPECTION LOW UTILIZATION ENGINE						Service ATA:72
	MOS	T:180 (+12m)		16-Apr-09	16-Apr-24	16-Apr-25	TOL (+343 d)	08-May-2024(2)
	HRS			0				
	ENC			0				
		REF: EMM 72-00-00						
25-64-13-200-801-01		INSPECTION OF THE LIFE RAFTS - LIFE RAFT (L7973ME)						Service ATA:25
PN:1218FAUL-7J0-1-608	MOS	36 (+3%)		26-Apr-21	26-Apr-24	28-May-24	TOL (+20 d)	08-May-2024
SN:12UL-02477	HRS							
	AFL							
		REF: AMM 25-64-13-200-801						
25-64-13-200-801-02		INSPECTION OF THE LIFE RAFTS - LIFE RAFT (R7973ME)						Service ATA:25
PN:1218FAUL-7J0-1-608	MOS	36 (+3%)		26-Apr-21	26-Apr-24	28-May-24	TOL (+20 d)	08-May-2024
SN:12UL-02263	HRS							
	AFL							
		REF: AMM 25-64-13-200-801						
72-00-20-280-801-01		NO. 1 ENGINE - INSPECTION LOW UTILIZATION ENGINE						Service ATA:72
	MOS	T:180 (+12m)		27-Apr-09	27-Apr-24	27-Apr-25	TOL (+354 d)	08-May-2024(2)
	HRS			0				
	ENC			0				
		REF: EMM 72-00-00						

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: FALCON 7X Serial: 107 RegNo: N542GP HRS: 2752.5 AFL: 1215 As Of: 23-Apr-2024 Operator: CLAY LACY AVIATION, INC.

Report Date: 08-May-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
72-00-20-280-801-01		NO. 3 ENGINE - INSPECTION LOW UTILIZATION ENGINE						Service ATA:72
	MOS	T:180 (+12m)		29-Apr-09	29-Apr-24	29-Apr-25	TOL (+356 d)	08-May-2024(2)
	HRS			0				
	ENC			0				
		REF: EMM 72-00-00						
28-00-00-910-803-01		DECONTAMINATION OF THE FUEL SYSTEMS - TREATMENT WITH A MINIMUM FUEL LOAD - FUEL INJECTION METHOD						Service ATA:28
	MOS	4 (+1m)		09-Jan-24	09-May-24	09-Jun-24	1 d (+31)	09-May-2024(6)
	HRS			2683				
	AFL			1191				
		REF: AMM 28-00-00-910-803						
24-50-01-710-801-01		OPERATIONAL TEST OF THE RAT TRANSFORMER RECTIFIER UNIT (TRU) - RAT TRU (2000PN)						Service ATA:24
	MOS	12 (+1m)	Adj:-14d	01-Jun-23	18-May-24	18-Jun-24	10 d (+31)	18-May-2024(2)
	HRS	400 (+10%)		2501.6	2901.6	2941.6	149.1 (+40)	
	AFL			1079				
		REF: AMM 24-50-01-710-801						
05-33-62-210-801-03		GENERAL VISUAL INSPECTION OF THE APU COMPARTMENT OVERFLOOR						Service ATA:05
	MOS	12 (+1m)		01-Jun-23	01-Jun-24	01-Jul-24	24 d (+30)	01-Jun-2024(2)
	HRS							
	AFL							
	APH	750 (+50)		2275	3025	3075	562 (+50)	
		REF: AMM 05-33-62-210-801						
05-37-00-210-803-05C		GENERAL VISUAL INSPECTION OF THE LANDING GEAR AREAS - GENERAL VISUAL INSPECTION OF THE LH MLG AREA (CPCP)						Service ATA:05
	MOS	12 (+1m)		01-Jun-23	01-Jun-24	01-Jul-24	24 d (+30)	01-Jun-2024(2)
	HRS			2501.6				
	AFL			1079				
		REF: AMM 05-37-00-210-803						
05-37-00-210-803-06C		GENERAL VISUAL INSPECTION OF THE LANDING GEAR AREAS - GENERAL VISUAL INSPECTION OF THE RH MLG AREA (CPCP)						Service ATA:05
	MOS	12 (+1m)		01-Jun-23	01-Jun-24	01-Jul-24	24 d (+30)	01-Jun-2024(2)
	HRS			2501.6				
	AFL			1079				
		REF: AMM 05-37-00-210-803						
05-37-00-210-803-07C		GENERAL VISUAL INSPECTION OF THE LANDING GEAR AREAS - GENERAL VISUAL INSPECTION OF THE NLG AREA AND BONDING BRAIDS (CPCP)						Service ATA:05
	MOS	12 (+1m)		01-Jun-23	01-Jun-24	01-Jul-24	24 d (+30)	01-Jun-2024(2)
	HRS			2501.6				
	AFL			1079				
		REF: AMM 05-37-00-210-803						

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: FALCON 7X Serial: 107 RegNo: N542GP HRS: 2752.5 AFL: 1215 As Of: 23-Apr-2024 Operator: CLAY LACY AVIATION, INC.

Report Date: 08-May-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est. Due
05-60-00-200-801-01		BASIC INSPECTION						Service ATA:05
	MOS	12 (+1m)		01-Jun-23	01-Jun-24	01-Jul-24	24 d (+30)	01-Jun-2024(2)
	HRS	400 (+40)		2501.6	2901.6	2941.6	149.1 (+40)	
	AFL			1079				
REF: MPD 05-10-00, AMM 05-60-00-200-801								
05-60-00-200-801-03		BASIC INSPECTION - GROUND SERVICING CHECKS						Service ATA:05
	MOS	12 (+1m)		01-Jun-23	01-Jun-24	01-Jul-24	24 d (+30)	01-Jun-2024(2)
	HRS	400 (+40)		2501.6	2901.6	2941.6	149.1 (+40)	
	AFL			1079				
REF: MPD 05-10-00, AMM 05-60-00-200-801								
21-53-00-720-801-01		FUNCTIONAL TEST OF THE EMERGENCY COLD AIR SUPPLY SYSTEM						Service ATA:21
	MOS	12 (+1m)		01-Jun-23	01-Jun-24	01-Jul-24	24 d (+30)	01-Jun-2024(2)
	HRS	600 (+50)		2501.6	3101.6	3151.6	349.1 (+50)	
	AFL			1079				
REF: AMM 21-53-00-720-801								
21-60-00-720-801-01		FUNCTIONAL TEST OF THE COCKPIT / CABIN MANUAL TEMPERATURE CONTROL FUNCTION						Service ATA:21
	MOS	12 (+1m)		01-Jun-23	01-Jun-24	01-Jul-24	24 d (+30)	01-Jun-2024(2)
	HRS	600 (+50)		2501.6	3101.6	3151.6	349.1 (+50)	
	AFL			1079				
REF: AMM 21-60-00-720-801								
24-32-01-760-801-01		CAPACITY TEST OF THE MAIN BATTERIES - BATTERY 1 (L1000PC)						Service ATA:24
PN:9750W0390-5	MOS	12 (+3%)		01-Jun-23	01-Jun-24	11-Jun-24	24 d (+10)	01-Jun-2024(2)
SN:19123W0004	HRS			2501.6				
	AFL			1079				
REF: AMM 24-32-01-760-801								
24-32-01-760-801-02		CAPACITY TEST OF THE MAIN BATTERIES - BATTERY 2 (R1000PC)						Service ATA:24
PN:9750W0390-5	MOS	12 (+3%)		01-Jun-23	01-Jun-24	11-Jun-24	24 d (+10)	01-Jun-2024(2)
SN:15009W0001	HRS			2501.6				
	AFL			1079				
REF: AMM 24-32-01-760-801								
25-61-00-200-881-01		INSPECTION OF THE EMERGENCY LOCATOR TRANSMITTER (ELT) SYSTEM (FAR 91.207)						Service ATA:25
	MOS	12		01-Jun-23	01-Jun-24		24 d	01-Jun-2024(2)
	HRS							
	AFL							
REF: GENERIC NO REF								
Disposition: MANDATORY								

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: FALCON 7X Serial: 107 RegNo: N542GP HRS: 2752.5 AFL: 1215 As Of: 23-Apr-2024 Operator: CLAY LACY AVIATION, INC.

Report Date: 08-May-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est. Due
25-64-21-220-801-01		DETAILED INSPECTION OF THE FIRST-AID KIT AND FIRST-AID KIT STOWAGE SYSTEM - DETAILED INSPECTION OF THE FIRST AID KIT						Service ATA:25
	MOS	DUE		01-Jun-23	01-Jun-24 (M)		24 d	01-Jun-2024
	HRS			2501.6				
	AFL			1079				
REF: AMM 25-64-21-220-801								
25-68-01-840-881-01		RESTORATION FIRST AID KIT						Service ATA:25
PN:500098	MOS	DUE		01-Jun-23	01-Jun-24 (M)		24 d	01-Jun-2024
SN:030422001	HRS			2501.6				
	AFL			1079				
REF: GENERIC NO REF								
33-50-05-350-801-01		RESTORATION OF THE DME EF-2C RECHARGEABLE FLASHLIGHTS (OVERHAUL) - LH FLASHLIGHT (L302ME)
						Service ATA:33
PN:P2-07-0009-520	MOS	12 (+3%)		01-Jun-23	01-Jun-24	11-Jun-24	24 d (+10)	01-Jun-2024(2)
SN:UNKNOWN	HRS			2501.6				
	AFL			1079				
Disposition: OVERHAUL REF: AMM 33-50-05-350-801								
33-50-05-350-801-02		RESTORATION OF THE DME EF-2C RECHARGEABLE FLASHLIGHTS (OVERHAUL) - RH FLASHLIGHT (R302ME)						Service ATA:33
PN:P2-07-0011-500	MOS	12 (+3%)		01-Jun-23	01-Jun-24	11-Jun-24	24 d (+10)	01-Jun-2024(2)
SN:NSN	HRS			2501.6				
	AFL			1079				
Disposition: OVERHAUL REF: AMM 33-50-05-350-801								
35-30-05-210-801-01		GENERAL VISUAL INSPECTION OF THE PORTABLE OXYGEN BOTTLE - PORTABLE OXYGEN KIT (702ME)						Service ATA:35
PN:894-20330	MOS	12 (+3%)		01-Jun-23	01-Jun-24	11-Jun-24	24 d (+10)	01-Jun-2024(2)
SN:P07070391	HRS			2501.6				
	AFL			1079				
REF: AMM 35-30-05-210-801								
38-10-00-670-801-01		STERILIZATION OF THE POTABLE WATER SYSTEM - STANDARD STERILIZATION						Service ATA:38
	MOS	6 (+1m)	Adj:-21d	22-Dec-23	01-Jun-24	01-Jul-24	24 d (+30)	01-Jun-2024(4)
	HRS			2659.9				
	AFL			1177				
REF: AMM 38-10-00-670-801								
49-81-04-220-801-01		DETAILED INSPECTION OF THE APU PRIMARY PIPE EXHAUST DUCT						Service ATA:49
	MOS	12 (+1m)		01-Jun-23	01-Jun-24	01-Jul-24	24 d (+30)	01-Jun-2024(2)
	HRS							
	AFL							
	APH	750 (+50)		2275	3025	3075	562 (+50)	
REF: AMM 49-81-04-220-801								

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: FALCON 7X Serial: 107 RegNo: N542GP HRS: 2752.5 AFL: 1215 As Of: 23-Apr-2024 Operator: CLAY LACY AVIATION, INC.

Report Date: 08-May-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	
52-80-09-640-801-03		LUBRICATION OF THE MAIN LANDING GEAR STRUT DOOR HINGE PINS - LH MLG STRUT DOOR HINGE PINS						Service	ATA:52
	MOS	12 (+1m)		01-Jun-23	01-Jun-24	01-Jul-24	24 d (+30)	01-Jun-2024(2)	
	HRS			2501.6					
	AFL	400		1079	1479		264		
REF: AMM 52-80-09-640-801									
52-80-09-640-801-04		LUBRICATION OF THE MAIN LANDING GEAR STRUT DOOR HINGE PINS - RH MLG STRUT DOOR HINGE PINS						Service	ATA:52
	MOS	12 (+1m)		01-Jun-23	01-Jun-24	01-Jul-24	24 d (+30)	01-Jun-2024(2)	
	HRS			2501.6					
	AFL	400		1079	1479		264		
REF: AMM 52-80-09-640-801									
55-10-33-640-801-01		LUBRICATION OF THE HORIZONTAL STABILIZER REAR HINGE PINS						Service	ATA:55
	MOS	12 (+1m)		01-Jun-23	01-Jun-24	01-Jul-24	24 d (+30)	01-Jun-2024(2)	
	HRS	600 (+50)		2501.6	3101.6	3151.6	349.1 (+50)		
	AFL			1079					
REF: AMM 55-10-33-640-801									
80-10-05-610-801-04		ENGINE PNEUMATIC STARTER OIL CHANGE - ENGINE 1 PNEUMATIC STARTER (L101EK)						Service	ATA:80
PN:3506034-4	MOS	12 (+3%)		01-Jun-23	01-Jun-24	11-Jun-24	24 d (+10)	01-Jun-2024(2)	
SN:467	HRS	600 (+3%)		2501.6	3101.6	3119.6	349.1 (+18)		
	AFL			1079					
REF: AMM 80-10-05-610-801									
80-10-05-610-801-05		ENGINE PNEUMATIC STARTER OIL CHANGE - ENGINE 2 PNEUMATIC STARTER (M101EK)						Service	ATA:80
PN:3506034-4	MOS	12 (+3%)		01-Jun-23	01-Jun-24	11-Jun-24	24 d (+10)	01-Jun-2024(2)	
SN:465	HRS	600 (+3%)		2501.6	3101.6	3119.6	349.1 (+18)		
	AFL			1079					
REF: AMM 80-10-05-610-801									
80-10-05-610-801-06		ENGINE PNEUMATIC STARTER OIL CHANGE - ENGINE 3 PNEUMATIC STARTER (R101EK)						Service	ATA:80
PN:3506034-4	MOS	12 (+3%)		01-Jun-23	01-Jun-24	11-Jun-24	24 d (+10)	01-Jun-2024(2)	
SN:470	HRS	600 (+3%)		2501.6	3101.6	3119.6	349.1 (+18)		
	AFL			1079					
REF: AMM 80-10-05-610-801									
27-53-01-640-801-01		LUBRICATION OF THE FLAP ACTUATOR SCREWS - LH INBOARD FLAP ACTUATOR 1 (L7003CF)						Service	ATA:27
	MOS	24 (+1m)		13-Jun-22	13-Jun-24	13-Jul-24	36 d (+30)	13-Jun-2024	
	HRS	1600 (+50)		2285.5	3885.5	3935.5	1133 (+50)		
	AFL	400		960	1360		145		
REF: AMM 27-53-01-640-801									

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: FALCON 7X Serial: 107 RegNo: N542GP HRS: 2752.5 AFL: 1215 As Of: 23-Apr-2024 Operator: CLAY LACY AVIATION, INC.

Report Date: 08-May-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
27-53-01-640-801-02		LUBRICATION OF THE FLAP ACTUATOR SCREWS - RH INBOARD FLAP ACTUATOR 1 (R7003CF)						Service ATA:27
	MOS	24 (+1m)		13-Jun-22	13-Jun-24	13-Jul-24	36 d (+30)	13-Jun-2024
	HRS	1600 (+50)		2285.5	3885.5	3935.5	1133 (+50)	
	AFL	400		960	1360		145	
		REF: AMM 27-53-01-640-801						
27-53-01-640-801-03		LUBRICATION OF THE FLAP ACTUATOR SCREWS - LH INBOARD FLAP ACTUATOR 2 (L7103CF)						Service ATA:27
	MOS	24 (+1m)		13-Jun-22	13-Jun-24	13-Jul-24	36 d (+30)	13-Jun-2024
	HRS	1600 (+50)		2285.5	3885.5	3935.5	1133 (+50)	
	AFL	400		960	1360		145	
		REF: AMM 27-53-01-640-801						
27-53-01-640-801-04		LUBRICATION OF THE FLAP ACTUATOR SCREWS - RH INBOARD FLAP ACTUATOR 2 (R7103CF)						Service ATA:27
	MOS	24 (+1m)		13-Jun-22	13-Jun-24	13-Jul-24	36 d (+30)	13-Jun-2024
	HRS	1600 (+50)		2285.5	3885.5	3935.5	1133 (+50)	
	AFL	400		960	1360		145	
		REF: AMM 27-53-01-640-801						
27-53-01-640-801-05		LUBRICATION OF THE FLAP ACTUATOR SCREWS - LH OUTBOARD FLAP ACTUATOR 3 (L7203CF)						Service ATA:27
	MOS	24 (+1m)		13-Jun-22	13-Jun-24	13-Jul-24	36 d (+30)	13-Jun-2024
	HRS	1600 (+50)		2285.5	3885.5	3935.5	1133 (+50)	
	AFL	400		960	1360		145	
		REF: AMM 27-53-01-640-801						
27-53-01-640-801-06		LUBRICATION OF THE FLAP ACTUATOR SCREWS - RH OUTBOARD FLAP ACTUATOR 3 (R7203CF)						Service ATA:27
	MOS	24 (+1m)		13-Jun-22	13-Jun-24	13-Jul-24	36 d (+30)	13-Jun-2024
	HRS	1600 (+50)		2285.5	3885.5	3935.5	1133 (+50)	
	AFL	400		960	1360		145	
		REF: AMM 27-53-01-640-801						
27-53-01-640-801-07		LUBRICATION OF THE FLAP ACTUATOR SCREWS - LH OUTBOARD FLAP ACTUATOR 4 (L7403CF)						Service ATA:27
	MOS	24 (+1m)		13-Jun-22	13-Jun-24	13-Jul-24	36 d (+30)	13-Jun-2024
	HRS	1600 (+50)		2285.5	3885.5	3935.5	1133 (+50)	
	AFL	400		960	1360		145	
		REF: AMM 27-53-01-640-801						
27-53-01-640-801-08		LUBRICATION OF THE FLAP ACTUATOR SCREWS - RH OUTBOARD FLAP ACTUATOR 4 (R7403CF)						Service ATA:27
	MOS	24 (+1m)		13-Jun-22	13-Jun-24	13-Jul-24	36 d (+30)	13-Jun-2024
	HRS	1600 (+50)		2285.5	3885.5	3935.5	1133 (+50)	
	AFL	400		960	1360		145	
		REF: AMM 27-53-01-640-801						

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: FALCON 7X Serial: 107 RegNo: N542GP HRS: 2752.5 AFL: 1215 As Of: 23-Apr-2024 Operator: CLAY LACY AVIATION, INC.

Report Date: 08-May-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
32-44-01-220-801-01		DETAILED INSPECTION OF THE NLG WHEEL HUBS - LH NLG WHEEL (L208GC)						Service ATA:32
	MOS			04-Oct-23				05-Jul-2024(4)
	HRS			2646.1				
	AFL	80		1159	1239		24	
		REF: AMM 32-44-01-220-801						
32-44-01-220-801-02		DETAILED INSPECTION OF THE NLG WHEEL HUBS - RH NLG WHEEL (R208GC)						Service ATA:32
	MOS			04-Oct-23				05-Jul-2024(4)
	HRS			2646.1				
	AFL	80		1159	1239		24	
		REF: AMM 32-44-01-220-801						
05-08-00-200-800-08		800FH INSPECTION						Package ATA:05
	MOS			14-Jul-21				21-Sep-2024
	HRS	800 (+40)		2027.5	2827.5	2867.5	75 (+40)	
	AFL			849				
		REF: MPD 05-10-00						
05-08-00-200-800-09		1600FH INSPECTION						Package ATA:05
	MOS			10-Apr-19				21-Sep-2024
	HRS	1600 (+40)	Adj:-66.6	1294.1	2827.5	2867.5	75 (+40)	
	AFL			573				
		REF: MPD 05-10-00						
32-10-00-640-801-01		LUBRICATION OF THE MAIN LANDING GEARS (MLG) AND MLG MAIN DOORS						Service ATA:32
	MOS	6 (+1m)		28-Mar-24	28-Sep-24	28-Oct-24	143 d (+30)	28-Sep-2024(4)
	HRS			2743.8				
	AFL	400		1211	1611		396	
		REF: AMM 32-10-00-640-801						
32-20-00-640-801-01		LUBRICATION OF THE NOSE LANDING GEAR (NLG) AND NLG DOORS						Service ATA:32
	MOS	6 (+1m)		28-Mar-24	28-Sep-24	28-Oct-24	143 d (+30)	28-Sep-2024(4)
	HRS			2743.8				
	AFL	400		1211	1611		396	
		REF: AMM 32-20-00-640-801						
32-44-00-640-801-01		LUBRICATION OF THE MLG AND NLG WHEEL BEARINGS - LH MLG OUTBOARD WHEEL (L609GC)						Service ATA:32
PN:90002745-4PSHMIC02	MOS	18 (+3%)		01-Jun-23	01-Dec-24	17-Dec-24	207 d (+16)	01-Dec-2024
SN:JAN13-1237	HRS			2501.6				
	AFL	400 (+3%)		1079	1479	1491	264 (+12)	
		REF: AMM 32-44-00-640-801						

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: FALCON 7X Serial: 107 RegNo: N542GP HRS: 2752.5 AFL: 1215 As Of: 23-Apr-2024 Operator: CLAY LACY AVIATION, INC.

Report Date: 08-May-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est. Due	
32-44-00-640-801-02		LUBRICATION OF THE MLG AND NLG WHEEL BEARINGS - LH MLG INBOARD WHEEL (L809GC)						Service	ATA:32
PN:90002745-4PSHMIC02	MOS	18 (+3%)		01-Jun-23	01-Dec-24	17-Dec-24	207 d (+16)	01-Dec-2024	
SN:FEB11-0861	HRS			2501.6					
	AFL	400 (+3%)		1079	1479	1491	264 (+12)		
REF: AMM 32-44-00-640-801									
32-44-00-640-801-03		LUBRICATION OF THE MLG AND NLG WHEEL BEARINGS - RH MLG INBOARD WHEEL (R809GC)						Service	ATA:32
PN:90002745-4PSHMIC02	MOS	18 (+3%)		01-Jun-23	01-Dec-24	17-Dec-24	207 d (+16)	01-Dec-2024	
SN:SEP19-1709	HRS			2501.6					
	AFL	400 (+3%)		1079	1479	1491	264 (+12)		
REF: AMM 32-44-00-640-801									
32-44-00-640-801-04		LUBRICATION OF THE MLG AND NLG WHEEL BEARINGS - RH MLG OUTBOARD WHEEL (R609GC)						Service	ATA:32
PN:90002745-4PSHMIC02	MOS	18 (+3%)		01-Jun-23	01-Dec-24	17-Dec-24	207 d (+16)	01-Dec-2024	
SN:MAR07-0223	HRS			2501.6					
	AFL	400 (+3%)		1079	1479	1491	264 (+12)		
REF: AMM 32-44-00-640-801									
32-44-00-640-801-05		LUBRICATION OF THE MLG AND NLG WHEEL BEARINGS - LH NLG WHEEL (L208GC)						Service	ATA:32
PN:90002746-1PSHMIC	MOS	18 (+3%)		01-Jun-23	01-Dec-24	17-Dec-24	207 d (+16)	01-Dec-2024	
SN:OCT06-0100	HRS			2501.6					
	AFL	400 (+3%)		1079	1479	1491	264 (+12)		
REF: AMM 32-44-00-640-801									
32-44-00-640-801-06		LUBRICATION OF THE MLG AND NLG WHEEL BEARINGS - RH NLG WHEEL (R208GC)						Service	ATA:32
PN:90002746-1PSHMIC	MOS	18 (+3%)		01-Jun-23	01-Dec-24	17-Dec-24	207 d (+16)	01-Dec-2024	
SN:MAY15-0955	HRS			2501.6					
	AFL	400 (+3%)		1079	1479	1491	264 (+12)		
REF: AMM 32-44-00-640-801									
27-50-00-710-802-01A		OPERATIONAL TEST OF THE FLAP BRAKE, AIRBRAKE LOCK AND SFAU POWER MONITOR (MANDATORY 5-40)						Service	ATA:27
	MOS			14-Jul-21				22-Dec-2024	
	HRS	850		2027.5	2877.5		125		
	AFL			849					
REF: AMM 27-50-00-710-802									
Disposition: CMR									
35-20-00-710-801-01A		OPERATIONAL TEST OF THE PASSENGER OXYGEN MODE SELECTOR INDICATION (MANDATORY 5-40)						Service	ATA:35
	MOS			14-Jul-21				22-Dec-2024	
	HRS	850		2027.5	2877.5		125		
	AFL			849					
REF: AMM 35-20-00-710-801									
Disposition: CMR									

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: FALCON 7X Serial: 107 RegNo: N542GP HRS: 2752.5 AFL: 1215 As Of: 23-Apr-2024 Operator: CLAY LACY AVIATION, INC.

Report Date: 08-May-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est. Due
24-20-05-710-801-01	OPERATIONAL TEST OF THE GROUND FAULT INTERRUPTER (GFI)							Service ATA:24
	MOS			13-Jun-22				05-Jan-2025
	HRS	600 (+50)		2285.5	2885.5	2935.5	133 (+50)	
	AFL			960				
	REF: AMM 24-20-05-710-801							
29-12-05-710-804-01	OPERATIONAL TEST OF THE HYDRAULIC FIREWALL SHUT-OFF VALVES - ENGINE 1 HYDRAULIC SYSTEM A SOV (L801GP)							Service ATA:29
	MOS	48 (+1m)		13-Jun-22	13-Jun-26	13-Jul-26	766 d (+30)	05-Jan-2025
	HRS	600 (+50)		2285.5	2885.5	2935.5	133 (+50)	
	AFL			960				
	REF: AMM 29-12-05-710-804							
29-12-05-710-804-02	OPERATIONAL TEST OF THE HYDRAULIC FIREWALL SHUT-OFF VALVES - ENGINE 3 HYDRAULIC SYSTEM A SOV (R801GP)							Service ATA:29
	MOS	48 (+1m)		13-Jun-22	13-Jun-26	13-Jul-26	766 d (+30)	05-Jan-2025
	HRS	600 (+50)		2285.5	2885.5	2935.5	133 (+50)	
	AFL			960				
	REF: AMM 29-12-05-710-804							
29-12-05-710-804-03	OPERATIONAL TEST OF THE HYDRAULIC FIREWALL SHUT-OFF VALVES - ENGINE 3 HYDRAULIC SYSTEM B SOV (R802GP)							Service ATA:29
	MOS	48 (+1m)		13-Jun-22	13-Jun-26	13-Jul-26	766 d (+30)	05-Jan-2025
	HRS	600 (+50)		2285.5	2885.5	2935.5	133 (+50)	
	AFL			960				
	REF: AMM 29-12-05-710-804							
29-12-05-710-804-04	OPERATIONAL TEST OF THE HYDRAULIC FIREWALL SHUT-OFF VALVES - ENGINE 2 HYDRAULIC SYSTEM B SOV (M802GP)							Service ATA:29
	MOS	48 (+1m)		13-Jun-22	13-Jun-26	13-Jul-26	766 d (+30)	05-Jan-2025
	HRS	600 (+50)		2285.5	2885.5	2935.5	133 (+50)	
	AFL			960				
	REF: AMM 29-12-05-710-804							
29-12-05-710-804-05	OPERATIONAL TEST OF THE HYDRAULIC FIREWALL SHUT-OFF VALVES - ENGINE 2 HYDRAULIC SYSTEM C SOV (803GP)							Service ATA:29
	MOS	48 (+1m)		13-Jun-22	13-Jun-26	13-Jul-26	766 d (+30)	05-Jan-2025
	HRS	600 (+50)		2285.5	2885.5	2935.5	133 (+50)	
	AFL			960				
	REF: AMM 29-12-05-710-804							
27-50-00-720-802-01	FUNCTIONAL TEST OF THE FLAP ASYMMETRY DETECTION CIRCUIT							Service ATA:27
	MOS			18-Jul-15				06-Feb-2025
	HRS	4800 (+50)		859.75	5659.75	5709.75	2907.3 (+50)	
	AFL	1000		328	1328		113	
	REF: AMM 27-50-00-720-802							

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: FALCON 7X Serial: 107 RegNo: N542GP HRS: 2752.5 AFL: 1215 As Of: 23-Apr-2024 Operator: CLAY LACY AVIATION, INC.

Report Date: 08-May-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	
27-53-01-720-801-01	FUNCTIONAL TEST OF THE FLAP ACTUATOR BACKLASH - LH INBOARD FLAP ACTUATOR 1 (L7003CF)							Service	ATA:27
	MOS			18-Jul-15				06-Feb-2025	
	HRS	4000		859.75	4859.75		2107.3		
	AFL	1000		328	1328		113		
	REF: AMM 27-53-01-720-801								
27-53-01-720-801-02	FUNCTIONAL TEST OF THE FLAP ACTUATOR BACKLASH - RH INBOARD FLAP ACTUATOR 1 (R7003CF)							Service	ATA:27
	MOS			18-Jul-15				06-Feb-2025	
	HRS	4000		859.75	4859.75		2107.3		
	AFL	1000		328	1328		113		
	REF: AMM 27-53-01-720-801								
27-53-01-720-801-03	FUNCTIONAL TEST OF THE FLAP ACTUATOR BACKLASH - LH INBOARD FLAP ACTUATOR 2 (L7103CF)							Service	ATA:27
	MOS			18-Jul-15				06-Feb-2025	
	HRS	4000		859.75	4859.75		2107.3		
	AFL	1000		328	1328		113		
	REF: AMM 27-53-01-720-801								
27-53-01-720-801-04	FUNCTIONAL TEST OF THE FLAP ACTUATOR BACKLASH - RH INBOARD FLAP ACTUATOR 2 (R7103CF)							Service	ATA:27
	MOS			18-Jul-15				06-Feb-2025	
	HRS	4000		859.75	4859.75		2107.3		
	AFL	1000		328	1328		113		
	REF: AMM 27-53-01-720-801								
27-53-01-720-801-05	FUNCTIONAL TEST OF THE FLAP ACTUATOR BACKLASH - LH OUTBOARD FLAP ACTUATOR 3 (L7203CF)							Service	ATA:27
	MOS			18-Jul-15				06-Feb-2025	
	HRS	4000		859.75	4859.75		2107.3		
	AFL	1000		328	1328		113		
	REF: AMM 27-53-01-720-801								
27-53-01-720-801-06	FUNCTIONAL TEST OF THE FLAP ACTUATOR BACKLASH - RH OUTBOARD FLAP ACTUATOR 3 (R7203CF)							Service	ATA:27
	MOS			18-Jul-15				06-Feb-2025	
	HRS	4000		859.75	4859.75		2107.3		
	AFL	1000		328	1328		113		
	REF: AMM 27-53-01-720-801								
27-53-01-720-801-07	FUNCTIONAL TEST OF THE FLAP ACTUATOR BACKLASH - LH OUTBOARD FLAP ACTUATOR 4 (L7403CF)							Service	ATA:27
	MOS			18-Jul-15				06-Feb-2025	
	HRS	4000		859.75	4859.75		2107.3		
	AFL	1000		328	1328		113		
	REF: AMM 27-53-01-720-801								



Due List Report

Model: FALCON 7X Serial: 107 RegNo: N542GP HRS: 2752.5 AFL: 1215 As Of: 23-Apr-2024 Operator: CLAY LACY AVIATION, INC.

Report Date: 08-May-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
27-53-01-720-801-08	FUNCTIONAL TEST OF THE FLAP ACTUATOR BACKLASH - RH OUTBOARD FLAP ACTUATOR 4 (R7403CF)							Service ATA:27
	MOS			18-Jul-15				06-Feb-2025
	HRS	4000		859.75	4859.75		2107.3	
	AFL	1000		328	1328		113	
	REF: AMM 27-53-01-720-801							
52-10-03-960-801-01	DISCARD OF THE PASSENGER DOOR PNEUMATIC ACTUATOR - PASSENGER DOOR PNEUMATIC ACTUATOR (200MA)							Service ATA:52
PN:222900-1M03	MOS	60	TAC:1	07-Apr-20	07-Mar-25		303 d	07-Mar-2025
SN:3479	HRS			1704.9				
	AFL			727				
Disposition: LIFE LIMIT	REF: AMM 52-10-03-960-801							
05-08-00-200-800-02	24M/1600FH INSPECTION							Package ATA:05
	MOS	24 (+1m)	Adj:-52d	01-Jun-23	10-Apr-25	10-May-25	337 d (+30)	10-Apr-2025
	HRS	1600 (+40)		2501.6	4101.6	4141.6	1349.1 (+40)	
	AFL			1079				
	REF: MPD 05-10-00							
05-08-00-200-800-03	36M/2400FH INSPECTION							Package ATA:05
	MOS	36 (+1m)	Adj:-64d	13-Jun-22	10-Apr-25	10-May-25	337 d (+30)	10-Apr-2025
	HRS	2400 (+40)	Adj:-583.9	2285.5	4101.6	4141.6	1349.1 (+40)	
	AFL			960				
	REF: MPD 05-10-00							
05-31-12-200-801-01C	INSPECTION OF THE LANDING GEAR BAYS - GENERAL VISUAL INSPECTION OF THE NLG BAY (CPCP)							Service ATA:05
	MOS	36 (+1m)	Adj:-64d	13-Jun-22	10-Apr-25	10-May-25	337 d (+30)	10-Apr-2025
	HRS			2285.5				
	AFL			960				
Disposition: CPCP	REF: AMM 05-31-12-200-801							
05-31-12-200-801-02C	INSPECTION OF THE LANDING GEAR BAYS - INSPECTION OF THE LH MLG BAY (CPCP)							Service ATA:05
	MOS	36 (+1m)	Adj:-64d	13-Jun-22	10-Apr-25	10-May-25	337 d (+30)	10-Apr-2025
	HRS			2285.5				
	AFL			960				
Disposition: CPCP	REF: AMM 05-31-12-200-801							
05-31-12-200-801-03C	INSPECTION OF THE LANDING GEAR BAYS - INSPECTION OF THE RH MLG BAY (CPCP)							Service ATA:05
	MOS	36 (+1m)	Adj:-64d	13-Jun-22	10-Apr-25	10-May-25	337 d (+30)	10-Apr-2025
	HRS			2285.5				
	AFL			960				
Disposition: CPCP	REF: AMM 05-31-12-200-801							

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: FALCON 7X Serial: 107 RegNo: N542GP HRS: 2752.5 AFL: 1215 As Of: 23-Apr-2024 Operator: CLAY LACY AVIATION, INC.

Report Date: 08-May-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est. Due	
05-35-61-200-801-01C		INSPECTION OF THE WING TRAILING EDGE - LH WING TRAILING EDGE (CPCP)						Service	ATA:05
	MOS	24 (+1m)	Adj:-52d	01-Jun-23	10-Apr-25	10-May-25	337 d (+30)	10-Apr-2025	
	HRS			2501.6					
	AFL								
Disposition: CPCP		REF: AMM 05-35-61-200-801							
05-35-61-200-801-02C		INSPECTION OF THE WING TRAILING EDGE - RH WING TRAILING EDGE (CPCP)						Service	ATA:05
	MOS	24 (+1m)	Adj:-52d	01-Jun-23	10-Apr-25	10-May-25	337 d (+30)	10-Apr-2025	
	HRS			2501.6					
	AFL								
Disposition: CPCP		REF: AMM 05-35-61-200-801							
27-50-00-220-801-01		DETAILED INSPECTION OF THE FLAP CONTROL SYSTEM						Service	ATA:27
	MOS	24 (+1m)	Adj:-52d	01-Jun-23	10-Apr-25	10-May-25	337 d (+30)	10-Apr-2025	
	HRS			2501.6					
	AFL	1000		1079	2079		864		
		REF: AMM 27-50-00-220-801							
27-53-01-610-801-01		SERVICING OF THE FLAP ACTUATORS - LH INBOARD FLAP ACTUATOR 1 (L7003CF)						Service	ATA:27
	MOS	24 (+1m)	Adj:-52d	01-Jun-23	10-Apr-25	10-May-25	337 d (+30)	10-Apr-2025	
	HRS			2501.6					
	AFL	1000		1079	2079		864		
		REF: AMM 27-53-01-610-801							
27-53-01-610-801-02		SERVICING OF THE FLAP ACTUATORS - RH INBOARD FLAP ACTUATOR 1 (R7003CF)						Service	ATA:27
	MOS	24 (+1m)	Adj:-52d	01-Jun-23	10-Apr-25	10-May-25	337 d (+30)	10-Apr-2025	
	HRS			2501.6					
	AFL	1000		1079	2079		864		
		REF: AMM 27-53-01-610-801							
27-53-01-610-801-03		SERVICING OF THE FLAP ACTUATORS - LH INBOARD FLAP ACTUATOR 2 (L7103CF)						Service	ATA:27
	MOS	24 (+1m)	Adj:-52d	01-Jun-23	10-Apr-25	10-May-25	337 d (+30)	10-Apr-2025	
	HRS			2501.6					
	AFL	1000		1079	2079		864		
		REF: AMM 27-53-01-610-801							
27-53-01-610-801-04		SERVICING OF THE FLAP ACTUATORS - RH INBOARD FLAP ACTUATOR 2 (R7103CF)						Service	ATA:27
	MOS	24 (+1m)	Adj:-52d	01-Jun-23	10-Apr-25	10-May-25	337 d (+30)	10-Apr-2025	
	HRS			2501.6					
	AFL	1000		1079	2079		864		
		REF: AMM 27-53-01-610-801							

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: FALCON 7X Serial: 107 RegNo: N542GP HRS: 2752.5 AFL: 1215 As Of: 23-Apr-2024 Operator: CLAY LACY AVIATION, INC.

Report Date: 08-May-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est. Due	
27-53-01-610-801-05		SERVICING OF THE FLAP ACTUATORS - LH OUTBOARD FLAP ACTUATOR 3 (L7203CF)						Service	ATA:27
	MOS	24 (+1m)	Adj:-52d	01-Jun-23	10-Apr-25	10-May-25	337 d (+30)	10-Apr-2025	
	HRS			2501.6					
	AFL	1000		1079	2079		864		
	REF: AMM 27-53-01-610-801								
27-53-01-610-801-06		SERVICING OF THE FLAP ACTUATORS - RH OUTBOARD FLAP ACTUATOR 3 (R7203CF)						Service	ATA:27
	MOS	24 (+1m)	Adj:-52d	01-Jun-23	10-Apr-25	10-May-25	337 d (+30)	10-Apr-2025	
	HRS			2501.6					
	AFL	1000		1079	2079		864		
	REF: AMM 27-53-01-610-801								
27-53-01-610-801-07		SERVICING OF THE FLAP ACTUATORS - LH OUTBOARD FLAP ACTUATOR 4 (L7403CF)						Service	ATA:27
	MOS	24 (+1m)	Adj:-52d	01-Jun-23	10-Apr-25	10-May-25	337 d (+30)	10-Apr-2025	
	HRS			2501.6					
	AFL	1000		1079	2079		864		
	REF: AMM 27-53-01-610-801								
27-53-01-610-801-08		SERVICING OF THE FLAP ACTUATORS - RH OUTBOARD FLAP ACTUATOR 4 (R7403CF)						Service	ATA:27
	MOS	24 (+1m)	Adj:-52d	01-Jun-23	10-Apr-25	10-May-25	337 d (+30)	10-Apr-2025	
	HRS			2501.6					
	AFL	1000		1079	2079		864		
	REF: AMM 27-53-01-610-801								
32-11-00-200-801-01C		DETAILED INSPECTION OF THE RUBBER SEALANT AROUND THE MLG BUSHING FLANGES - LH MLG DRESSED (L1003GA) (CPCP)						Service	ATA:32
	MOS	36 (+1m)	Adj:-64d	13-Jun-22	10-Apr-25	10-May-25	337 d (+30)	10-Apr-2025	
	HRS			2285.5					
	AFL			960					
Disposition: CPCP	REF: AMM 32-11-00-200-801								
32-11-00-200-801-02C		DETAILED INSPECTION OF THE RUBBER SEALANT AROUND THE MLG BUSHING FLANGES - RH MLG DRESSED (R1003GA) (CPCP)						Service	ATA:32
	MOS	36 (+1m)	Adj:-64d	13-Jun-22	10-Apr-25	10-May-25	337 d (+30)	10-Apr-2025	
	HRS			2285.5					
	AFL			960					
Disposition: CPCP	REF: AMM 32-11-00-200-801								
32-11-05-780-801-01		CHECK OF THE CHARGING PRESSURE OF THE MLG SHOCK ABSORBERS - LH MLG SHOCK ABSORBER (L203GA)						Service	ATA:32
	MOS	24 (+1m)	Adj:-52d	01-Jun-23	10-Apr-25	10-May-25	337 d (+30)	10-Apr-2025	
	HRS			2501.6					
	AFL	1000		1079	2079		864		
	REF: AMM 32-11-05-780-801								

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: FALCON 7X Serial: 107 RegNo: N542GP HRS: 2752.5 AFL: 1215 As Of: 23-Apr-2024 Operator: CLAY LACY AVIATION, INC.

Report Date: 08-May-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est. Due	
32-11-05-780-801-02		CHECK OF THE CHARGING PRESSURE OF THE MLG SHOCK ABSORBERS - RH MLG SHOCK ABSORBER (R203GA)						Service	ATA:32
	MOS	24 (+1m)	Adj:-52d	01-Jun-23	10-Apr-25	10-May-25	337 d (+30)	10-Apr-2025	
	HRS			2501.6					
	AFL	1000		1079	2079		864		
REF: AMM 32-11-05-780-801									
32-21-00-200-801-01C		DETAILED INSPECTION OF THE RUBBER SEALANT AROUND THE NLG BUSHING FLANGES (CPCP)						Service	ATA:32
	MOS	36 (+1m)	Adj:-64d	13-Jun-22	10-Apr-25	10-May-25	337 d (+30)	10-Apr-2025	
	HRS			2285.5					
	AFL			960					
REF: AMM 32-21-00-200-801									
Disposition: CPCP									
32-21-01-780-801-01		CHECK OF THE CHARGING PRESSURE OF THE NLG SHOCK ABSORBER - NLG SHOCK ABSORBER (1001GB)						Service	ATA:32
	MOS	24 (+1m)	Adj:-52d	01-Jun-23	10-Apr-25	10-May-25	337 d (+30)	10-Apr-2025	
	HRS			2501.6					
	AFL	1000		1079	2079		864		
REF: AMM 32-21-01-780-801									
53-50-00-210-802-06C		GENERAL VISUAL INSPECTION FROM OUTSIDE OF THE BAGGAGE COMPARTMENT SKIN UPPER PART (CPCP)						Service	ATA:53
	MOS	36 (+1m)	Adj:-64d	13-Jun-22	10-Apr-25	10-May-25	337 d (+30)	10-Apr-2025	
	HRS			2285.5					
	AFL			960					
REF: AMM 53-50-00-210-802									
Disposition: CPCP									
32-44-17-220-801-01		DETAILED INSPECTION OF THE BRAKE HEAT SINK - LH OUTBOARD BRAKE (L1209GC)						Service	ATA:32
PN:90010325	MOS			13-Jun-22				25-Apr-2025	
SN:JAN09-0494	HRS			2285.5					
	AFL	400 (+3%)		960	1360	1372	145 (+12)		
REF: AMM 32-44-17-220-801									
32-44-17-220-801-03		DETAILED INSPECTION OF THE BRAKE HEAT SINK - RH INBOARD BRAKE (R1409GC)						Service	ATA:32
PN:90010325	MOS			13-Jun-22				25-Apr-2025	
SN:AUG08-0459	HRS			2285.5					
	AFL	400 (+3%)		960	1360	1372	145 (+12)		
REF: AMM 32-44-17-220-801									
32-44-17-220-801-04		DETAILED INSPECTION OF THE BRAKE HEAT SINK - RH OUTBOARD BRAKE (R1209GC)						Service	ATA:32
PN:90010325	MOS			13-Jun-22				25-Apr-2025	
SN:MAR12-0913	HRS			2285.5					
	AFL	400 (+3%)		960	1360	1372	145 (+12)		
REF: AMM 32-44-17-220-801									

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: FALCON 7X Serial: 107 RegNo: N542GP HRS: 2752.5 AFL: 1215 As Of: 23-Apr-2024 Operator: CLAY LACY AVIATION, INC.

Report Date: 08-May-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est. Due	
25-62-00-350-801-01		RESTORATION OF THE FDR / CVR UNDERWATER LOCATOR BEACONS INCLUDING BATTERY CHANGE - FDR/CVR 1 UNDERWATER LOCATOR BEACON (9500FZ)						Service	ATA:25
PN:165003	MOS	DUE		27-Nov-19	01-May-25 (M)		358 d	01-May-2025	
SN:ULB024065	HRS			1534.8					
	AFL								
Disposition: LIFE LIMIT		REF: AMM 25-62-00-350-801							
25-62-00-350-801-02		RESTORATION OF THE FDR / CVR UNDERWATER LOCATOR BEACONS INCLUDING BATTERY CHANGE - FDR/CVR 2 UNDERWATER LOCATOR BEACON (9501FZ)						Service	ATA:25
PN:1650003	MOS	DUE		27-Nov-19	01-May-25 (M)		358 d	01-May-2025	
SN:ULB023895	HRS			1534.8					
	AFL								
Disposition: LIFE LIMIT		REF: AMM 25-62-00-350-801							
24-50-01-710-801-01A		OPERATIONAL TEST OF THE RAT TRANSFORMER RECTIFIER UNIT (TRU) - RAT TRU (2000PN) (MANDATORY 5-40)						Service	ATA:24
	MOS			01-Jun-23				06-May-2025	
	HRS	450		2501.6	2951.6		199.1		
	AFL			1079					
Disposition: CMR		REF: AMM 24-50-01-710-801							
24-32-01-710-802-01		OPERATIONAL TEST OF THE MAIN BATTERY THERMOSTAT - BATTERY 1 (L1000PC)						Service	ATA:24
PN:9750W0390-5	MOS	24 (+3%)		01-Jun-23	01-Jun-25	22-Jun-25	389 d (+21)	01-Jun-2025	
SN:19123W0004	HRS	1800 (+50)		2501.6	4301.6	4351.6	1549.1 (+50)		
	AFL			1079					
		REF: AMM 24-32-01-710-802							
24-32-01-710-802-02		OPERATIONAL TEST OF THE MAIN BATTERY THERMOSTAT - BATTERY 2 (R1000PC)						Service	ATA:24
PN:9750W0390-5	MOS	24 (+3%)		01-Jun-23	01-Jun-25	22-Jun-25	389 d (+21)	01-Jun-2025	
SN:15009W0001	HRS	1800 (+50)		2501.6	4301.6	4351.6	1549.1 (+50)		
	AFL			1079					
		REF: AMM 24-32-01-710-802							
24-32-01-960-801-01		REBLOCKING OF THE MAIN BATTERIES - BATTERY 1 (L1000PC)						Service	ATA:24
PN:9750W0390-5	MOS	24 (+3%)		01-Jun-23	01-Jun-25	22-Jun-25	389 d (+21)	01-Jun-2025	
SN:19123W0004	HRS			2501.6					
	AFL			1079					
		REF: AMM 24-32-01-960-801							
24-32-01-960-801-02		REBLOCKING OF THE MAIN BATTERIES - BATTERY 2 (R1000PC)						Service	ATA:24
PN:9750W0390-5	MOS	24 (+3%)		01-Jun-23	01-Jun-25	22-Jun-25	389 d (+21)	01-Jun-2025	
SN:15009W0001	HRS			2501.6					
	AFL			1079					
		REF: AMM 24-32-01-960-801							

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: FALCON 7X Serial: 107 RegNo: N542GP HRS: 2752.5 AFL: 1215 As Of: 23-Apr-2024 Operator: CLAY LACY AVIATION, INC.

Report Date: 08-May-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	
26-20-09-780-801-01		FUNCTIONAL CHECK OF THE PRESSURE OF THE FIRE EXTINGUISHERS - FIRE EXTINGUISHER 1 (1001WB)						Service	ATA:26
PN:10053-04	MOS	24 (+3%)		01-Jun-23	01-Jun-25	22-Jun-25	389 d (+21)	01-Jun-2025	
SN:RR00233	HRS	1600 (+3%)		2501.6	4101.6	4149.6	1349.1 (+48)		
	AFL			1079					
REF: AMM 26-20-09-780-801									
26-20-09-780-801-02		FUNCTIONAL CHECK OF THE PRESSURE OF THE FIRE EXTINGUISHERS - FIRE EXTINGUISHER 2 (2001WB)						Service	ATA:26
PN:10053-04	MOS	24 (+3%)		01-Jun-23	01-Jun-25	22-Jun-25	389 d (+21)	01-Jun-2025	
SN:RR00266	HRS	1600 (+3%)		2501.6	4101.6	4149.6	1349.1 (+48)		
	AFL			1079					
REF: AMM 26-20-09-780-801									
26-20-09-780-801-03		FUNCTIONAL CHECK OF THE PRESSURE OF THE FIRE EXTINGUISHERS - FIRE EXTINGUISHER 3 (3001WB)						Service	ATA:26
PN:10700-03	MOS	24 (+3%)		01-Jun-23	01-Jun-25	22-Jun-25	389 d (+21)	01-Jun-2025	
SN:RT00004	HRS	1600 (+3%)		2501.6	4101.6	4149.6	1349.1 (+48)		
	AFL			1079					
REF: AMM 26-20-09-780-801									
26-20-09-780-801-04		FUNCTIONAL CHECK OF THE PRESSURE OF THE FIRE EXTINGUISHERS - FIRE EXTINGUISHER 4 (4001WB)						Service	ATA:26
PN:10052-04	MOS	24 (+3%)		01-Jun-23	01-Jun-25	22-Jun-25	389 d (+21)	01-Jun-2025	
SN:RS000198	HRS	1600 (+3%)		2501.6	4101.6	4149.6	1349.1 (+48)		
	AFL			1079					
REF: AMM 26-20-09-780-801									
26-20-15-720-801-01		WEIGHING OF THE PORTABLE FIRE EXTINGUISHERS - COCKPIT PORTABLE FIRE EXTINGUISHER (218WB)						Service	ATA:26
PN:898052	MOS	24 (+3%)		01-Jun-23	01-Jun-25	22-Jun-25	389 d (+21)	01-Jun-2025	
SN:F67876122	HRS								
	AFL								
REF: AMM 26-20-15-720-801									
26-20-15-720-801-02		WEIGHING OF THE PORTABLE FIRE EXTINGUISHERS - FWD CABIN PORTABLE FIRE EXTINGUISHER (418WB)						Service	ATA:26
PN:898052	MOS	24 (+3%)		01-Jun-23	01-Jun-25	22-Jun-25	389 d (+21)	01-Jun-2025	
SN:F67876126	HRS								
	AFL								
REF: AMM 26-20-15-720-801									
26-20-15-720-801-03		WEIGHING OF THE PORTABLE FIRE EXTINGUISHERS - AFT CABIN PORTABLE FIRE EXTINGUISHER (618WB)						Service	ATA:26
PN:466090	MOS	24 (+3%)		01-Jun-23	01-Jun-25	22-Jun-25	389 d (+21)	01-Jun-2025	
SN:E68033340	HRS								
	AFL								
REF: AMM 26-20-15-720-801									

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: FALCON 7X Serial: 107 RegNo: N542GP HRS: 2752.5 AFL: 1215 As Of: 23-Apr-2024 Operator: CLAY LACY AVIATION, INC.

Report Date: 08-May-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
33-50-37-960-801-01 DISCARD OF THE EPS BATTERY PACKS - BATTERY PACK 1 (9500LE) Service ATA:33								
PN:4395153Y00	MOS	24		01-Jun-23	01-Jun-25		389 d	01-Jun-2025
SN:UNKNOWN	HRS			2501.6				
	AFL			1079				
Disposition: LIFE LIMIT			REF: AMM 33-50-37-960-801					
34-18-01-700-881-01 TEST STATIC PRESSURE SYSTEM (FAR 91.411) Service ATA:34								
	MOS	24		01-Jun-23	01-Jun-25		389 d	01-Jun-2025
	HRS			2501.6				
	AFL			1079				
Disposition: MANDATORY			REF: GENERIC NO REF					
34-18-01-700-882-01 TEST RH LOWER AIR DATA SMART PROBE (FAR 91.411) Service ATA:34								
	MOS	24		01-Jun-23	01-Jun-25		389 d	01-Jun-2025
	HRS			2501.6				
	AFL			1079				
Disposition: MANDATORY			REF: GENERIC NO REF					
34-18-01-700-882-02 TEST LH LOWER AIR DATA SMART PROBE (FAR 91.411) Service ATA:34								
	MOS	24		01-Jun-23	01-Jun-25		389 d	01-Jun-2025
	HRS			2501.6				
	AFL			1079				
Disposition: MANDATORY			REF: GENERIC NO REF					
34-18-01-700-882-03 TEST RH UPPER AIR DATA SMART PROBE (FAR 91.411) Service ATA:34								
	MOS	24		01-Jun-23	01-Jun-25		389 d	01-Jun-2025
	HRS			2501.6				
	AFL			1079				
Disposition: MANDATORY			REF: GENERIC NO REF					
34-18-01-700-882-04 TEST LH UPPER AIR DATA SMART PROBE (FAR 91.411) Service ATA:34								
	MOS	24		01-Jun-23	01-Jun-25		389 d	01-Jun-2025
	HRS			2501.6				
	AFL			1079				
Disposition: MANDATORY			REF: GENERIC NO REF					
34-54-00-720-802-01 FUNCTIONAL TEST OF THE AIR TRAFFIC CONTROL (ATC) SYSTEM - ATC 1 SYSTEM (105NR) Service ATA:34								
PN:7517402-970	MOS	24 (+3%)		01-Jun-23	01-Jun-25	22-Jun-25	389 d (+21)	01-Jun-2025
SN:0701C195	HRS			2501.6				
	AFL			1079				
Disposition: RVSM			REF: AMM 34-54-00-720-802					

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: FALCON 7X Serial: 107 RegNo: N542GP HRS: 2752.5 AFL: 1215 As Of: 23-Apr-2024 Operator: CLAY LACY AVIATION, INC.

Report Date: 08-May-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
34-54-00-720-802-02		FUNCTIONAL TEST OF THE AIR TRAFFIC CONTROL (ATC) SYSTEM - ATC 2 SYSTEM (205NR)						Service ATA:34
PN:7517402-970	MOS	24 (+3%)		01-Jun-23	01-Jun-25	22-Jun-25	389 d (+21)	01-Jun-2025
SN:0606B313	HRS			2501.6				
	AFL			1079				
Disposition: RVSM		REF: AMM 34-54-00-720-802						
34-54-05-700-881-01		TEST NO. 1 AIR TRAFFIC CONTROL (ATC) MODULAR RADIO CABINET (MRC) TRANSPONDER MODULE (FAR 91.413)						Service ATA:34
PN:7517402-970	MOS	24		01-Jun-23	01-Jun-25		389 d	01-Jun-2025
SN:0701C195	HRS			2501.6				
	AFL			1079				
Disposition: MANDATORY		REF: GENERIC NO REF						
34-54-05-700-881-02		TEST NO. 2 AIR TRAFFIC CONTROL (ATC) MODULAR RADIO CABINET (MRC) TRANSPONDER MODULE (FAR 91.413)						Service ATA:34
PN:7517402-970	MOS	24		01-Jun-23	01-Jun-25		389 d	01-Jun-2025
SN:0606B313	HRS			2501.6				
	AFL			1079				
Disposition: MANDATORY		REF: GENERIC NO REF						
32-44-17-220-801-02		DETAILED INSPECTION OF THE BRAKE HEAT SINK - LH INBOARD BRAKE (L1409GC)						Service ATA:32
PN:90010325	MOS			16-Aug-22				15-Jun-2025
SN:APR12-0298	HRS			2325.9				
	AFL	400 (+3%)		981	1381	1393	166 (+12)	
		REF: AMM 32-44-17-220-801						
32-44-17-220-801-02A		DETAILED INSPECTION OF THE BRAKE HEAT SINK - LH INBOARD BRAKE (L1409GC) (MANDATORY 5-40)						Service ATA:32
PN:90010325	MOS			16-Aug-22				15-Jun-2025
SN:APR12-0298	HRS			2325.9				
	AFL	400		981	1381		166	
Disposition: CMR		REF: AMM 32-44-17-220-801						
27-40-00-710-802-01A		OPERATIONAL TEST OF THE HSTA TRIM EMERG CONTROL (MANDATORY 5-40)						Service ATA:27
	MOS			14-Jul-21				21-Sep-2025
	HRS	1000		2027.5	3027.5		275	
	AFL			849				
Disposition: CMR		REF: AMM 27-40-00-710-802						
24-50-00-720-801-01A		FUNCTIONAL TEST OF THE RAT SYSTEM (MANDATORY 5-40)						Service ATA:24
	MOS	28		01-Jun-23	01-Oct-25		511 d	01-Oct-2025
	HRS	1850		2501.6	4351.6		1599.1	
	AFL			1079				
Disposition: CMR		REF: AMM 24-50-00-720-801						

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: FALCON 7X Serial: 107 RegNo: N542GP HRS: 2752.5 AFL: 1215 As Of: 23-Apr-2024 Operator: CLAY LACY AVIATION, INC.

Report Date: 08-May-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est. Due	
28-50-00-760-801-01A		CHECK OF THE GROUNDING CONNECTOR ELECTRICAL BONDING (MANDATORY 5-40)						Service	ATA:28
	MOS	40		13-Jun-22	13-Oct-25		523 d	13-Oct-2025	
	HRS			2285.5					
	AFL			960					
Disposition: ALI / CDCCL		REF: AMM 28-50-00-760-801							
27-91-01-710-802-01		OPERATIONAL TEST OF THE SIDESTICK DASH-POTS - LH PILOT SIDESTICK (101CK)						Service	ATA:27
PN:0CV196-07	MOS			13-Jun-22				25-Dec-2025	
SN:124	HRS			2285.5					
	AFL	500 (+3%)		960	1460	1475	245 (+15)		
		REF: AMM 27-91-01-710-802							
27-91-01-710-802-02		OPERATIONAL TEST OF THE SIDESTICK DASH-POTS - RH PILOT SIDESTICK (201CK)						Service	ATA:27
PN:0CV197-08	MOS			13-Jun-22				25-Dec-2025	
SN:130	HRS			2285.5					
	AFL	500 (+3%)		960	1460	1475	245 (+15)		
		REF: AMM 27-91-01-710-802							
33-50-37-960-801-02		DISCARD OF THE EPS BATTERY PACKS - BATTERY PACK 2 (9510LE)						Service	ATA:33
PN:4395153Y00	MOS	24	TAC:1	25-Jan-24	25-Dec-25		596 d	25-Dec-2025	
SN:N/A	HRS		TAC:0	2692.4					
	AFL		TAC:0	1195					
Disposition: LIFE LIMIT		REF: AMM 33-50-37-960-801							
33-50-37-960-801-03		DISCARD OF THE EPS BATTERY PACKS - BATTERY PACK 3 (9520LE)						Service	ATA:33
PN:4395153Y00	MOS	24	TAC:1	25-Jan-24	25-Dec-25		596 d	25-Dec-2025	
SN:N/A	HRS		TAC:0	2692.4					
	AFL		TAC:0	1195					
Disposition: LIFE LIMIT		REF: AMM 33-50-37-960-801							
57-41-00-220-802-01		DETAILED INSPECTION OF THE SYNCHRONIZATION MECHANISM						Service	ATA:57
	MOS			13-Jun-22				25-Dec-2025	
	HRS			2285.5					
	AFL	500		960	1460		245		
		REF: AMM 57-41-00-220-802							
27-30-01-350-801-04		RESTORATION OF THE ELEVATOR ACTUATORS (OVERHAUL WITH SEAL REPLACEMENT) - RH ELEVATOR OUTBOARD SERVO-ACTUATOR (R201CP)						Service	ATA:27
PN:103154-16	MOS	216 (+3%)		01-Jan-08	01-Jan-26	15-Jul-26	603 d (+195)	01-Jan-2026	
SN:227	HRS								
	AFL								
Disposition: OVERHAUL		REF: AMM 27-30-01-350-801							

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: FALCON 7X Serial: 107 RegNo: N542GP HRS: 2752.5 AFL: 1215 As Of: 23-Apr-2024 Operator: CLAY LACY AVIATION, INC.

Report Date: 08-May-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
27-52-01-610-801-01	SERVICING OF THE POWER DRIVE UNIT							Service ATA:27
	MOS	48 (+1m)		05-Jan-22	05-Jan-26	05-Feb-26	607 d (+31)	05-Jan-2026
	HRS			2136.7				
	AFL	2000		911	2911		1696	
	REF: AMM 27-52-01-610-801							
27-52-05-610-801-01	SERVICING OF THE FLAP TRANSMISSION GEARBOXES - LH 14° FLAP GEARBOX (3802CF)							Service ATA:27
	MOS	48 (+1m)		05-Jan-22	05-Jan-26	05-Feb-26	607 d (+31)	05-Jan-2026
	HRS			2136.7				
	AFL	2000		911	2911		1696	
	REF: AMM 27-52-05-610-801							
27-52-05-610-801-02	SERVICING OF THE FLAP TRANSMISSION GEARBOXES - RH 14° FLAP GEARBOX (4002CF)							Service ATA:27
	MOS	48 (+1m)		05-Jan-22	05-Jan-26	05-Feb-26	607 d (+31)	05-Jan-2026
	HRS			2136.7				
	AFL	2000		911	2911		1696	
	REF: AMM 27-52-05-610-801							
27-52-05-610-801-03	SERVICING OF THE FLAP TRANSMISSION GEARBOXES - LH UPPER 90° FLAP GEARBOX (L3502CF)							Service ATA:27
	MOS	48 (+1m)		05-Jan-22	05-Jan-26	05-Feb-26	607 d (+31)	05-Jan-2026
	HRS			2136.7				
	AFL	2000		911	2911		1696	
	REF: AMM 27-52-05-610-801							
27-52-05-610-801-04	SERVICING OF THE FLAP TRANSMISSION GEARBOXES - RH UPPER 90° FLAP GEARBOX (R3502CF)							Service ATA:27
	MOS	48 (+1m)		05-Jan-22	05-Jan-26	05-Feb-26	607 d (+31)	05-Jan-2026
	HRS			2136.7				
	AFL	2000		911	2911		1696	
	REF: AMM 27-52-05-610-801							
27-52-05-610-801-05	SERVICING OF THE FLAP TRANSMISSION GEARBOXES - LH LOWER 90° FLAP GEARBOX (L3602CF)							Service ATA:27
	MOS	48 (+1m)		05-Jan-22	05-Jan-26	05-Feb-26	607 d (+31)	05-Jan-2026
	HRS			2136.7				
	AFL	2000		911	2911		1696	
	REF: AMM 27-52-05-610-801							
27-52-05-610-801-06	SERVICING OF THE FLAP TRANSMISSION GEARBOXES - RH LOWER 90° FLAP GEARBOX (R3602CF)							Service ATA:27
	MOS	48 (+1m)		05-Jan-22	05-Jan-26	05-Feb-26	607 d (+31)	05-Jan-2026
	HRS			2136.7				
	AFL	2000		911	2911		1696	
	REF: AMM 27-52-05-610-801							



Due List Report

Model: FALCON 7X Serial: 107 RegNo: N542GP HRS: 2752.5 AFL: 1215 As Of: 23-Apr-2024 Operator: CLAY LACY AVIATION, INC.

Report Date: 08-May-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est. Due
05-08-10-200-800-11		NO. 1 ENGINE - 600 HOUR INSPECTION						Package ATA:05
	MOS			01-Jun-23				01-Feb-2026
	HRS	600 (+30)		2407.4	(3007.4)3100	3037.4	347.5 (+30)	
	ENC			1025				
REF: EMM 05-20-00								
05-08-10-200-800-11		NO. 2 ENGINE - 600 HOUR INSPECTION						Package ATA:05
	MOS			01-Jun-23				01-Feb-2026
	HRS	600 (+30)		2456.3	(3056.3)3100	3086.3	347.5 (+30)	
	ENC			1044				
REF: EMM 05-20-00								
05-08-10-200-800-11		NO. 3 ENGINE - 600 HOUR INSPECTION						Package ATA:05
	MOS			01-Jun-23				01-Feb-2026
	HRS	600 (+30)		2456.3	(3056.3)3100	3086.3	347.5 (+30)	
	ENC			1044				
REF: EMM 05-20-00								
57-45-00-200-802-12		INSPECTION OF THE SLATS - LH MIDDLE SLAT (L9501CM)						Service ATA:57
PN:F7XC57450000S2	MOS	96 (+3%)		08-Mar-18	08-Mar-26	04-Jun-26	669 d (+88)	08-Mar-2026
SN:SA3037	HRS							
	AFL							
REF: AMM 57-45-00-200-802								
57-45-00-200-802-12C		INSPECTION OF THE SLATS - LH MIDDLE SLAT (L9501CM) (CPCP)						Service ATA:57
PN:F7XC57450000S2	MOS	96 (+3%)		08-Mar-18	08-Mar-26	04-Jun-26	669 d (+88)	08-Mar-2026
SN:SA3037	HRS							
	AFL							
REF: AMM 57-45-00-200-802								
Disposition: CPCP								
49-81-05-220-801-01		DETAILED INSPECTION OF THE APU EXHAUST MUFFLER ASSEMBLY - APU EXHAUST MUFFLER ASSEMBLY (501KE)						Service ATA:49
PN:7083602-4	MOS	36 (+1m)	Adj:-56d	01-Jun-23	06-Apr-26	06-May-26	698 d (+30)	06-Apr-2026
SN:UNKNOWN	HRS							
	AFL							
	APH	750 (+50)		2275	3025	3075	562 (+50)	
REF: AMM 49-81-05-220-801								
36-10-00-710-802-01A		OPERATIONAL TEST OF THE DISTRIBUTION / BLEED AIR SYSTEM (MANIFOLD PRESSURE REGULATING AND SHUT-OFF VALVES) - ENGINE 1 MANIFOLD PRSOV (2501HU) (MANDATORY 5-40)						Service ATA:36
	MOS			10-Apr-19				22-Apr-2026
	HRS	1850		1294.1	3144.1		391.6	
	AFL			573				
REF: AMM 36-10-00-710-802								
Disposition: CMR								

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: FALCON 7X Serial: 107 RegNo: N542GP HRS: 2752.5 AFL: 1215 As Of: 23-Apr-2024 Operator: CLAY LACY AVIATION, INC.

Report Date: 08-May-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est. Due	
36-10-00-710-802-02A		OPERATIONAL TEST OF THE DISTRIBUTION / BLEED AIR SYSTEM (MANIFOLD PRESSURE REGULATING AND SHUT-OFF VALVES) - ENGINE 2 MANIFOLD PRSOV (2601HU) (MANDATORY 5-40)						Service	ATA:36
	MOS			10-Apr-19				22-Apr-2026	
	HRS	1850		1294.1	3144.1		391.6		
	AFL			573					
Disposition: CMR		REF: AMM 36-10-00-710-802							
36-10-00-710-802-03A		OPERATIONAL TEST OF THE DISTRIBUTION / BLEED AIR SYSTEM (MANIFOLD PRESSURE REGULATING AND SHUT-OFF VALVES) - ENGINE 3 MANIFOLD PRSOV (2701HU) (MANDATORY 5-40)						Service	ATA:36
	MOS			10-Apr-19				22-Apr-2026	
	HRS	1850		1294.1	3144.1		391.6		
	AFL			573					
Disposition: CMR		REF: AMM 36-10-00-710-802							
26-20-13-960-801-06		DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - FIRE EXTINGUISHER 3 GREEN CARTRIDGE (3201WB)						Service	ATA:26
PN:10650-01	MOS	120		01-May-16	01-May-26		723 d	01-May-2026	
SN:TP0996	HRS								
	AFL								
Disposition: LIFE LIMIT		REF: AMM 26-20-13-960-801							
21-53-00-720-801-01A		FUNCTIONAL TEST OF THE EMERGENCY COLD AIR SUPPLY SYSTEM (MANDATORY 5-40)						Service	ATA:21
	MOS			01-Jun-23				06-May-2026	
	HRS	650		2501.6	3151.6		399.1		
	AFL			1079					
Disposition: CMR		REF: AMM 21-53-00-720-801							
21-60-00-720-801-01A		FUNCTIONAL TEST OF THE COCKPIT / CABIN MANUAL TEMPERATURE CONTROL FUNCTION (MANDATORY 5-40)						Service	ATA:21
	MOS			01-Jun-23				06-May-2026	
	HRS	650		2501.6	3151.6		399.1		
	AFL			1079					
Disposition: CMR		REF: AMM 21-60-00-720-801							
35-10-01-350-801-02		RESTORATION (OVERHAUL) OF THE CREW OXYGEN MASK REGULATORS, GOGGLES AND STOWAGE BOXES - REGULATOR OF THE RH CREW OXYGEN MASK (R2002WH)						Service	ATA:35
PN:MLD40-45-005	MOS	72	TAC:14	06-Jul-21	06-May-26		728 d	06-May-2026	
SN:B158478	HRS	4800 (+100)	TAC:0	2027.5	6827.5	6927.5	4075 (+100)		
	AFL			849					
Disposition: OVERHAUL		REF: AMM 35-10-01-350-801							

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: FALCON 7X Serial: 107 RegNo: N542GP HRS: 2752.5 AFL: 1215 As Of: 23-Apr-2024 Operator: CLAY LACY AVIATION, INC.

Report Date: 08-May-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est. Due	
35-10-01-350-801-02A		RESTORATION (OVERHAUL) OF THE CREW OXYGEN MASK REGULATORS, GOGGLES AND STOWAGE BOXES - REGULATOR OF THE RH CREW OXYGEN MASK (R2002WH) (MANDATORY 5-40)						Service	ATA:35
PN:MLD40-45-005	MOS	72	TAC:14	06-Jul-21	06-May-26		728 d	06-May-2026	
SN:B158478	HRS	4900	TAC:0	2027.5	6927.5		4175		
	AFL			849					
Disposition: CMR		REF: AMM 35-10-01-350-801							
35-10-01-350-801-03		RESTORATION (OVERHAUL) OF THE CREW OXYGEN MASK REGULATORS, GOGGLES AND STOWAGE BOXES - REGULATOR OF THE THIRD CREW MEMBER OXYGEN MASK (M2002WH)						Service	ATA:35
PN:MLD40-45-005	MOS	72	TAC:14	06-Jul-21	06-May-26		728 d	06-May-2026	
SN:B158483	HRS	4800 (+100)	TAC:0	2027.5	6827.5	6927.5	4075 (+100)		
	AFL			849					
Disposition: OVERHAUL		REF: AMM 35-10-01-350-801							
35-10-01-350-801-03A		RESTORATION (OVERHAUL) OF THE CREW OXYGEN MASK REGULATORS, GOGGLES AND STOWAGE BOXES - REGULATOR OF THE THIRD CREW MEMBER OXYGEN MASK (M2002WH) (MANDATORY 5-40)						Service	ATA:35
PN:MLD40-45-005	MOS	72	TAC:14	06-Jul-21	06-May-26		728 d	06-May-2026	
SN:B158483	HRS	4900	TAC:0	2027.5	6927.5		4175		
	AFL			849					
Disposition: CMR		REF: AMM 35-10-01-350-801							