



DueList Report

HONDAJET HA-420 ELITE

S/N 42000138 N542MP

OWNER: AVIATION HOLDINGS SERVICES LTD ADDRESS: AMS LIMITED ST PETER JE3 7BY OFFICE: FAX:	OPERATOR: CLAY LACY AVIATION, INC. ADDRESS: 7435 VALJEAN AVENUE VAN NUYS CA 91406 OFFICE: 818-947-5407 FAX: 818-947-5470	OPERATOR: AMS LIMITED ADDRESS: GIBRALTAR FARM, LE MONT DES VIGNES ST. PETER JERSEY OFFICE: 44-1534-748020 FAX:	CAMO: THURSTON AVIATION LTD ADDRESS: HANGAR 427 BUSINESS PARK WEST CHRISTCHURCH DORSET BH23 6EA OFFICE: 07415984631 FAX:
ANALYST: ERIC FOSTER EMAIL: EFOSTER@CAMPSYSTEMS.COM	+1-316-928-7887 (DIRECT) +1-631-588-3200 (MAIN) WWW.CAMPSYSTEMS.COM	800-787-9749 (EFAX-CARDS) 631-980-4222 (EFAX-CARDS)	

PROJECTED: 24 MOS. to 30-SEP-2026

AIRCRAFT	SERIAL/REGNO: 42000138/N542MP	MODEL: HONDAJET HA-420 ELITE	MANUFACTURER: HONDA AIRCRAFT COMPANY, INC.
	CERTIFICATION DATE: 04-FEB-2019	LAST ACTUALS: 1531.8 A/C HRS as of 15-SEP-2024 1644 AFL as of 15-SEP-2024	PROJECTED: 1931.80 2044

ENGINE NO. 1	SERIAL/PART: 883389/HJ1-17201-120-003	MODEL: HF120-H1A	MANUFACTURER: GE HONDA AERO ENGINES
	INSTALLED ON: 27-NOV-2023 1157.5 ENG. HRS 1212.3 A/C HRS 1218 ENC	LAST ACTUALS: 1477 ENG. HRS as of 15-SEP-2024 1523 ENC as of 15-SEP-2024	PROJECTED: 1877 1923

ENGINE NO. 2	SERIAL/PART: 883388/HJ1-17201-120-004	MODEL: HF120-H1A	MANUFACTURER: GE HONDA AERO ENGINES
	INSTALLED ON: 27-NOV-2023 1157.5 ENG. HRS 1212.3 A/C HRS 1218 ENC	LAST ACTUALS: 1477 ENG. HRS as of 15-SEP-2024 1523 ENC as of 15-SEP-2024	PROJECTED: 1877 1923



# New Requirement/Flagged Items

Operator Review and Action Required

Model: HONDAJET HA-420 ELITE Serial: 42000138 RegNo: N542MP HRS: 1531.8 AFL: 1644 As Of: 15-Sep-2024 Operator: CLAY LACY AVIATION, INC.

Report Date: 20-Sep-2024

These tasks or requirements have been added newly to your aircraft status. Please review them and approve or modify as appropriate. Please pay particular attention to the Base and Next Due Times for these tasks. It is important to note that any task that has insufficient information (marked by ?), will never come due unless the necessary information is provided by you.

PN & SN	Effective Date	Unit	Interval	Base Time		Next Due (ENG/APU) A/C	Disposition
				Current	Change To		
SB 420-53-009		FUSELAGE - SKIN DAMAGE - REPAIR, SERVICE BULLETIN					Bulletin ATA:53
		MOS		04-Feb-19	_____		MANDATORY
		HRS			_____	1800 * (M)	
		AFL	T:6000	0	_____	6000 *	
NEW REQUIREMENT ADDED ON 01-SEP-24. RENEW BASE TIMES TO ENSURE CORRECT DUE TIMES.				REF: BULLETINS			
52CA5211130		MAIN ENTRY DOOR (MED) HINGE PLATE FASTENERS - REPLACE					Service ATA:52
	30-Jun-24	MOS		04-Feb-19	_____		
		HRS			_____		
		AFL	9000	0 (EBT)	_____	9000 *	
NEW REQUIREMENT ADDED ON 13-AUG-24. RENEW BASE TIMES TO ENSURE CORRECT DUE TIMES.				REF:			
56CA5611111		LEFT WINDSHIELD FASTENERS - REPLACE					Service ATA:56
	30-Jun-24	MOS		04-Feb-19	_____		
		HRS			_____		
		AFL	10000	0 (EBT)	_____	10000 *	
NEW REQUIREMENT ADDED ON 13-AUG-24. RENEW BASE TIMES TO ENSURE CORRECT DUE TIMES.				REF: AMM 56-11-10			
56CA5611112		RIGHT WINDSHIELD FASTENERS - REPLACE					Service ATA:56
	30-Jun-24	MOS		04-Feb-19	_____		
		HRS			_____		
		AFL	10000	0 (EBT)	_____	10000 *	
NEW REQUIREMENT ADDED ON 13-AUG-24. RENEW BASE TIMES TO ENSURE CORRECT DUE TIMES.				REF: AMM 56-11-10			
56CA5611113		LEFT COCKPIT SIDE WINDOW - REPLACE					Service ATA:56
	30-Jun-24	MOS		04-Feb-19	_____		
		HRS			_____		
		AFL	14000	0 (EBT)	_____	14000 *	
NEW REQUIREMENT ADDED ON 13-AUG-24. RENEW BASE TIMES TO ENSURE CORRECT DUE TIMES.				REF: AMM 56-11-11			
56CA5611114		RIGHT COCKPIT SIDE WINDOW - REPLACE					Service ATA:56
	30-Jun-24	MOS		04-Feb-19	_____		
		HRS			_____		
		AFL	14000	0 (EBT)	_____	14000 *	
NEW REQUIREMENT ADDED ON 13-AUG-24. RENEW BASE TIMES TO ENSURE CORRECT DUE TIMES.				REF: AMM 56-11-11			

Name: \_\_\_\_\_ Signature: \_\_\_\_\_ Cert.# \_\_\_\_\_ Date: \_\_\_\_\_

?-Insufficient Information S -Suppressed Requirement \* -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



## Due List Report

Model: HONDAJET HA-420 ELITE Serial: 42000138 RegNo: N542MP HRS: 1531.8  
 AFL: 1644 As Of: 15-Sep-2024 Operator: CLAY LACY AVIATION, INC.

Report Date: 20-Sep-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est. Due	
24CA2430013		NO. 1 MAIN SHIP (LEAD ACID) BATTERY MAIN SHIP (LEAD ACID) BATTERY CAPACITY CHECK							Service ATA:24
PN:RG-145-1	MOS	6 (+1m/-1m)		07-Feb-24	RTS-OVD				
SN:41121567	HRS								
	AFL								
REF: AMM 12-11-18, CMM 24-30-71								WO#: N542MP-240916-1	
27HA2711102		AILERON TRIM TAB BACKLASH - DETAILED INSPECTION							Service ATA:27
	MOS			25-Aug-23	RTS-OVD				
	HRS	300		1160.7					
	AFL			1249					
Disposition: AIRWORTHINESS								REF: AMM 27-10-01	
REF: AMM 27-10-01								WO#: N542MP-240916-1	
34HA3410102		DO THE FUNCTIONAL TEST OF THE PRIMARY AIR DATA SYSTEM. REFER TO THE CURRENT 14 CFR 14 CFR 91.411 AND 91.413 REQUIREMENT OR LOCAL REGULATORY AUTHORITY							Service ATA:34
PN:2015T-1B	MOS	24 (+30d/-30d)		30-Sep-22	30-Sep-24	30-Oct-24	10 d (+30)	30-Sep-2024(2)	
SN:0275	HRS			940.3					
	AFL			996					
Disposition: AIRWORTHINESS								REF: AMM 34-00-02	
REF: AMM 34-00-02								WO#: N542MP-240916-1	
34HA3410102		DO THE FUNCTIONAL TEST OF THE STANDBY AIR DATA SYSTEM. REFER TO THE CURRENT 14 CFR 14 CFR 91.411 AND 91.413 REQUIREMENT OR LOCAL REGULATORY AUTHORITY							Service ATA:34
PN:2015T-1B	MOS	24 (+30d/-30d)		30-Sep-22	30-Sep-24	30-Oct-24	10 d (+30)	30-Sep-2024(2)	
SN:0261	HRS			940.3					
	AFL			996					
Disposition: AIRWORTHINESS								REF: AMM 34-00-02	
REF: AMM 34-00-02								WO#: N542MP-240916-1	
34HA3410103		DO THE FUNCTIONAL TEST OF THE NO. 1 TRANSPONDER. REFER TO THE CURRENT 14 CFR 14 CFR 91.411 AND 91.413 REQUIREMENT OR LOCAL REGULATORY AUTHORITY							Service ATA:34
PN:011-01997-00	MOS	24 (+30d/-30d)		30-Sep-22	30-Sep-24	30-Oct-24	10 d (+30)	30-Sep-2024(2)	
SN:20S008762	HRS								
	AFL								
REF: AMM 34-00-02								WO#: N542MP-240916-1	
34HA3410103		DO THE FUNCTIONAL TEST OF THE NO. 2 TRANSPONDER. REFER TO THE CURRENT 14 CFR 14 CFR 91.411 AND 91.413 REQUIREMENT OR LOCAL REGULATORY AUTHORITY							Service ATA:34
PN:011-01997-00	MOS	24 (+30d/-30d)		30-Sep-22	30-Sep-24	30-Oct-24	10 d (+30)	30-Sep-2024(2)	
SN:20S008760	HRS								
	AFL								
REF: AMM 34-00-02								WO#: N542MP-240916-1	
25CA2521500		FIRST AID KIT							Component ATA:25
PN:PN	MOS	O/C		25-Aug-23	31-Oct-24 (M)		41 d	31-Oct-2024	
SN:UNKNOWN	HRS			1160.7					

?-Insufficient Information S -Suppressed Requirement \* -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



## Due List Report

Model: HONDAJET HA-420 ELITE Serial: 42000138 RegNo: N542MP HRS: 1531.8  
AFL: 1644 As Of: 15-Sep-2024 Operator: CLAY LACY AVIATION, INC.

Report Date: 20-Sep-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est. Due	
	AFL			1249					
REF: GENERIC NO REF									
24CA2430013		NO. 2 MAIN SHIP (LEAD ACID) BATTERY MAIN SHIP (LEAD ACID) BATTERY CAPACITY CHECK						Service	ATA:24
PN:RG-390ES	MOS	T:12 (+1m/-1m)		25-Jan-24	31-Jan-25	25-Feb-25	133 d (+25)	31-Jan-2025(4)	
SN:41295135	HRS								
	AFL								
REF: AMM 12-11-18, CMM 24-30-71									
12HA1221102		LUBRICATE LEFT MAIN LANDING GEAR. REFER TO SCHEDULED SERVICING SECTION						Service	ATA:12
	MOS			20-Aug-24				03-Feb-2025(3)	
	HRS	150 (+10%/-10%)	Adj:-27.9	1483.6	1605.7	1620.7	73.9 (+15)		
	AFL			1603					
REF: AMM 12-21-12									
12HA1221102		LUBRICATE NOSE LANDING GEAR. REFER TO SCHEDULED SERVICING SECTION						Service	ATA:12
	MOS			20-Aug-24				03-Feb-2025(3)	
	HRS	150 (+10%/-10%)	Adj:-27.9	1483.6	1605.7	1620.7	73.9 (+15)		
	AFL			1603					
REF: AMM 12-21-12									
12HA1221102		LUBRICATE RIGHT MAIN LANDING GEAR. REFER TO SCHEDULED SERVICING SECTION						Service	ATA:12
	MOS			20-Aug-24				03-Feb-2025(3)	
	HRS	150 (+10%/-10%)	Adj:-27.9	1483.6	1605.7	1620.7	73.9 (+15)		
	AFL			1603					
REF: AMM 12-21-12									
25HA2563062		EMERGENCY LOCATOR TRANSMITTER SELF-TEST (ELT) P/N S182X502-XX, S185X501-XX						Service	ATA:25
PN:S1851501-01	MOS	6 (+30d/-30d)	Adj:-13d	20-Aug-24	28-Feb-25	09-Mar-25	161 d (+9)	28-Feb-2025(4)	
SN:LX1101111355	HRS			1483.6					
	AFL			1603					
REF: CMM 25-63-08, AMM 25-60-01									
53HA5300103		DO THE INSPECTION OF THE FORWARD FUSELAGE AND THE RVSM CRITICAL ZONE.						Service	ATA:53
	MOS	24 (+30d/-30d)	Adj:1d	09-Feb-23	28-Feb-25	12-Mar-25	161 d (+12)	28-Feb-2025	
	HRS			1053.6					
	AFL			1128					
REF: AMM 53-00-01									
25HA2560102		EMERGENCY LOCATOR TRANSMITTER FUNCTIONAL TEST. P/N S185X501-XX (KIT S1840510-02)						Service	ATA:25
PN:S1851501-01	MOS	12 (+30d/-30d)	Adj:-7d	05-Aug-24	31-Jul-25	28-Aug-25	314 d (+28)	31-Jul-2025(2)	
SN:LX1101111355	HRS			1442.7					
	AFL			1576					
REF: CMM 25-63-08, AMM 25-60-01									

?-Insufficient Information S -Suppressed Requirement \* -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



## Due List Report

Model: HONDAJET HA-420 ELITE Serial: 42000138 RegNo: N542MP HRS: 1531.8  
 AFL: 1644 As Of: 15-Sep-2024 Operator: CLAY LACY AVIATION, INC.

Report Date: 20-Sep-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est. Due
26HA2620101		FWD HANDHELD FIRE EXTINGUISHER VISUAL INSPECTION P/N RT A1200 OR 337TS (OPTIONAL) (F.S. 140.70 LEFT SIDE)						Service ATA:26
PN:RT A1200	MOS	12 (+30d/-30d)		20-Aug-24	31-Aug-25	19-Sep-25	345 d (+19)	31-Aug-2025(2)
SN:Y-501886	HRS			1483.6				
	AFL			1603				
REF: ALIM INTRO								WO#: N542MP-240916-1
26HA2620102		AFT HANDHELD FIRE EXTINGUISHER VISUAL INSPECTION P/N RT A1200 OR 337TS (OPTIONAL) (F.S. 258.50 LEFT SIDE)						Service ATA:26
PN:RT A1200	MOS	12 (+30d/-30d)		20-Aug-24	31-Aug-25	19-Sep-25	345 d (+19)	31-Aug-2025(2)
SN:Y-4995B4	HRS			1483.6				
	AFL			1603				
REF: ALIM INTRO								WO#: N542MP-240916-1
34HA3411102		DO THE ALIGNMENT INSPECTION OF THE AIR DATA PROBES FOR RVSM.						Service ATA:34
	MOS	24 (+30d/-30d)		25-Aug-23	31-Aug-25	24-Sep-25	345 d (+24)	31-Aug-2025
	HRS			1160.7				
	AFL			1249				
REF: AMM 34-11-00								
Disposition: RVSM								
35CA3521121		POSITION 1A PASSENGER MASK DEPLOYMENT SYSTEM CARTRIDGE (P/N HA4-330845) - VISUAL INSPECTION						Service ATA:35
PN:HJ1-13520-301-001	MOS	24 (+30d/-30d)		25-Aug-23	31-Aug-25	24-Sep-25	345 d (+24)	31-Aug-2025
SN:D18051269	HRS			1160.7				
	AFL			1249				
REF: CMM 35-20-22, AMM 35-21-10								
35CA3521122		POSITION 1B PASSENGER MASK (OPTIONAL EQUIPMENT) DEPLOYMENT SYSTEM CARTRIDGE (P/N HA4-330845) - VISUAL INSPECTION						Service ATA:35
PN:HJ1-13520-301-001	MOS	24 (+30d/-30d)		25-Aug-23	31-Aug-25	24-Sep-25	345 d (+24)	31-Aug-2025
SN:D18051265	HRS			1160.7				
	AFL			1249				
REF: CMM 35-20-22, AMM 35-21-10								
35CA3521123		POSITION 2A PASSENGER MASK DEPLOYMENT SYSTEM CARTRIDGE (P/N HA4-330845) - VISUAL INSPECTION						Service ATA:35
PN:HJ1-13520-301-001	MOS	24 (+30d/-30d)		25-Aug-23	31-Aug-25	24-Sep-25	345 d (+24)	31-Aug-2025
SN:D18051264	HRS			1160.7				
	AFL			1249				
REF: CMM 35-20-22, AMM 35-21-10								
35CA3521124		POSITION 2B PASSENGER MASK DEPLOYMENT SYSTEM CARTRIDGE (P/N HA4-330845) - VISUAL INSPECTION						Service ATA:35
PN:PN	MOS	24 (+30d/-30d)		25-Aug-23	31-Aug-25	24-Sep-25	345 d (+24)	31-Aug-2025
SN:UNKNOWN	HRS			1160.7				
	AFL			1249				
REF: CMM 35-20-22, AMM 35-21-10								

?-Insufficient Information S -Suppressed Requirement \* -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



## Due List Report

Model: HONDAJET HA-420 ELITE Serial: 42000138 RegNo: N542MP HRS: 1531.8  
AFL: 1644 As Of: 15-Sep-2024 Operator: CLAY LACY AVIATION, INC.

Report Date: 20-Sep-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est. Due	
35CA3521125		POSITION 3A PASSENGER MASK DEPLOYMENT SYSTEM CARTRIDGE (P/N HA4-330845) - VISUAL INSPECTION						Service	ATA:35
PN:PN	MOS	24 (+30d/-30d)		25-Aug-23	31-Aug-25	24-Sep-25	345 d (+24)	31-Aug-2025	
SN:UNKNOWN	HRS			1160.7					
	AFL			1249					
REF: CMM 35-20-22, AMM 35-21-10									
35CA3521126		POSITION 3B PASSENGER MASK DEPLOYMENT SYSTEM CARTRIDGE (P/N HA4-330845) - VISUAL INSPECTION						Service	ATA:35
PN:PN	MOS	24 (+30d/-30d)		25-Aug-23	31-Aug-25	24-Sep-25	345 d (+24)	31-Aug-2025	
SN:UNKNOWN	HRS			1160.7					
	AFL			1249					
REF: CMM 35-20-22, AMM 35-21-10									
35CA3521127		POSITION 4A PASSENGER MASK DEPLOYMENT SYSTEM CARTRIDGE (P/N HA4-330845) - VISUAL INSPECTION						Service	ATA:35
PN:PN	MOS	24 (+30d/-30d)		25-Aug-23	31-Aug-25	24-Sep-25	345 d (+24)	31-Aug-2025	
SN:UNKNOWN	HRS			1160.7					
	AFL			1249					
REF: CMM 35-20-22, AMM 35-21-10									
23HA2350101		CREW COMMUNICATION SYSTEM: OXYGEN MICROPHONE AND SWITCHES - OPERATIONAL TEST						Service	ATA:23
	MOS			25-Aug-23				17-Nov-2025	
	HRS	600 (+60/-60)		1160.7	1760.7	1820.7	228.9 (+60)		
	AFL			1249					
REF: AMM 23-50-01									
Disposition: AIRWORTHINESS									
24CA2430122		LEFT STARTER / GENERATOR BRUSH INSPECTION. - VISUAL INSPECT						Service	ATA:24
PN:HJ1-12435-101-002	MOS			25-Aug-23				17-Nov-2025	
SN:0343	HRS	600 (+60/-60)		1160.7	1760.7	1820.7	228.9 (+60)		
	AFL			1249					
REF: CMM 24-30-12, ALIM INTRO, CMM 24-30-25									
24CA2430122		RIGHT STARTER / GENERATOR BRUSH INSPECTION. - VISUAL INSPECT						Service	ATA:24
PN:MG94J-1	MOS			25-Aug-23				17-Nov-2025	
SN:0109	HRS	600 (+10%/-10%)		1160.7	1760.7	1820.7	228.9 (+60)		
	AFL			1249					
REF: CMM 24-30-12, ALIM INTRO, CMM 24-30-25									
24HA2400101		ELECTRICAL POWER SYSTEM: BUS TIE CONTACT SWITCH - OPERATIONAL TEST						Service	ATA:24
	MOS			25-Aug-23				17-Nov-2025	
	HRS	600 (+60/-60)		1160.7	1760.7	1820.7	228.9 (+60)		
	AFL			1249					
REF: AMM 24-00-01									
Disposition: AIRWORTHINESS									

?-Insufficient Information S -Suppressed Requirement \* -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



## Due List Report

Model: HONDAJET HA-420 ELITE Serial: 42000138 RegNo: N542MP HRS: 1531.8  
AFL: 1644 As Of: 15-Sep-2024 Operator: CLAY LACY AVIATION, INC.

Report Date: 20-Sep-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est. Due
24HA2400101		ELECTRICAL POWER SYSTEM: CABIN POWER SWITCH CONTACT - OPERATIONAL TEST						Service ATA:24
	MOS			25-Aug-23				17-Nov-2025
	HRS	600 (+60/-60)		1160.7	1760.7	1820.7	228.9 (+60)	
	AFL			1249				
Disposition: AIRWORTHINESS		REF: AMM 24-00-01						
27HA2721103		RUDDER TRIM TAB BACKLASH - DETAILED INSPECTION						Service ATA:27
	MOS			25-Aug-23				17-Nov-2025
	HRS	600 (+60/-60)		1160.7	1760.7	1820.7	228.9 (+60)	
	AFL			1249				
Disposition: AIRWORTHINESS		REF: AMM 27-20-01						
27HA2731103		ELEVATOR TRIM TAB BACKLASH - DETAILED INSPECTION						Service ATA:27
	MOS			25-Aug-23				17-Nov-2025
	HRS	600 (+60/-60)		1160.7	1760.7	1820.7	228.9 (+60)	
	AFL			1249				
Disposition: AIRWORTHINESS		REF: AMM 27-30-01						
27HA2750103		LEFT FLAP BALL SCREW - DETAILED INSPECTION						Service ATA:27
PN:HJ1-12750-810-009	MOS			25-Aug-23				17-Nov-2025
SN:288	HRS	600		1160.7	1760.7		228.9	
	AFL			1249				
Disposition: AIRWORTHINESS		REF: AMM 27-50-01						
27HA2750103		RIGHT FLAP BALL SCREW - DETAILED INSPECTION						Service ATA:27
PN:HJ1-12750-810-009	MOS			25-Aug-23				17-Nov-2025
SN:289	HRS	600		1160.7	1760.7		228.9	
	AFL			1249				
Disposition: AIRWORTHINESS		REF: AMM 27-50-01						
28HA0500105		SURGE TANK FLOAT SWITCH - DETAILED INSPECTION						Service ATA:28
	MOS			25-Aug-23				17-Nov-2025
	HRS	600 (+60/-60)		1160.7	1760.7	1820.7	228.9 (+60)	
	AFL			1249				
Disposition: AIRWORTHINESS		REF: AMM 28-00-05						
29HA2900107		HYDRAULIC POWER SYSTEM - FUNCTIONAL TEST						Service ATA:29
	MOS			25-Aug-23				17-Nov-2025
	HRS	600 (+60/-60)		1160.7	1760.7	1820.7	228.9 (+60)	
	AFL			1249				
Disposition: AIRWORTHINESS		REF: AMM 29-00-01						

?-Insufficient Information S -Suppressed Requirement \* -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



## Due List Report

Model: HONDAJET HA-420 ELITE Serial: 42000138 RegNo: N542MP HRS: 1531.8  
 AFL: 1644 As Of: 15-Sep-2024 Operator: CLAY LACY AVIATION, INC.

Report Date: 20-Sep-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est. Due
30HA3010103		OPERATIONAL TEST OF THE WING ICE PROTECTION SYSTEM (WAIV HIGH FLOW SOLENOID)						Service ATA:30
	MOS			25-Aug-23				17-Nov-2025
	HRS	600 (+60/-60)		1160.7	1760.7	1820.7	228.9 (+60)	
	AFL			1249				
REF: AMM 30-10-01								
30HA3020102		BLEED AIR LEAK DETECTION SYSTEM (OVER TEMPERATURE SWITCH) - FUNCTIONAL TEST						Service ATA:30
	MOS			25-Aug-23				17-Nov-2025
	HRS	600 (+60/-60)		1160.7	1760.7	1820.7	228.9 (+60)	
	AFL			1249				
Disposition: AIRWORTHINESS REF: AMM 30-20-02								
30HA3040101		WINDSHIELD TEMPERATURE SENSING SYSTEM - FUNCTIONAL TEST						Service ATA:30
	MOS			25-Aug-23				17-Nov-2025
	HRS	600 (+60/-60)		1160.7	1760.7	1820.7	228.9 (+60)	
	AFL			1249				
Disposition: AIRWORTHINESS REF: AMM 30-40-01								
32HA3200103		EMERGENCY EXTENSION SYSTEM & NOSE LANDING GEAR UPLOCK - FUNCTIONAL TEST						Service ATA:32
	MOS			25-Aug-23				17-Nov-2025
	HRS	600 (+60/-60)		1160.7	1760.7	1820.7	228.9 (+60)	
	AFL			1249				
Disposition: AIRWORTHINESS REF: AMM 32-00-01, AMM 32-00-02								
32HA3240102		LANDING GEAR LATENT FAILURES, DIGITAL ANTI-SKID CONTROL UNIT (DACU) ANNUNCIATION - FUNCTIONAL TEST						Service ATA:32
	MOS			25-Aug-23				17-Nov-2025
	HRS	600 (+60/-60)		1160.7	1760.7	1820.7	228.9 (+60)	
	AFL			1249				
Disposition: AIRWORTHINESS REF: AMM 32-40-02								
34HA3400104		TRAFFIC COLLISION AVOIDANCE SYSTEM - FUNCTIONAL TEST						Service ATA:34
PN:011-02571-00	MOS			25-Aug-23				17-Nov-2025
SN:28P007736	HRS	600 (+60/-60)		1160.7	1760.7	1820.7	228.9 (+60)	
	AFL			1249				
Disposition: AIRWORTHINESS REF: AMM 34-00-02								
35HA0500101		VISUAL INSPECTION OF THE PASSENGER OXYGEN SYSTEM (BROKEN FILLER CAP)						Service ATA:35
	MOS			25-Aug-23				17-Nov-2025
	HRS	600 (+60/-60)		1160.7	1760.7	1820.7	228.9 (+60)	
	AFL			1249				
Disposition: AIRWORTHINESS REF: ALIM INTRO								

?-Insufficient Information S -Suppressed Requirement \* -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time





## Due List Report

Model: HONDAJET HA-420 ELITE Serial: 42000138 RegNo: N542MP HRS: 1531.8  
AFL: 1644 As Of: 15-Sep-2024 Operator: CLAY LACY AVIATION, INC.

Report Date: 20-Sep-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est. Due
35HA3500101		FUNCTIONAL CHECK OF THE PASSENGER OXYGEN SYSTEM (GENERAL)						Service ATA:35
	MOS			25-Aug-23				17-Nov-2025
	HRS	600 (+60/-60)		1160.7	1760.7	1820.7	228.9 (+60)	
	AFL			1249				
Disposition: AIRWORTHINESS		REF: AMM 35-00-01						
35HA3500102		FUNCTIONAL CHECK OF THE PASSENGER OXYGEN SYSTEM (OXYGEN SERVICE PANEL LEAK, WITH CAP REMOVED AT SERVICE PANEL)						Service ATA:35
	MOS			25-Aug-23				17-Nov-2025
	HRS	600 (+60/-60)		1160.7	1760.7	1820.7	228.9 (+60)	
	AFL			1249				
Disposition: AIRWORTHINESS		REF: AMM 35-00-02						
35HA3500103		PASSENGER OXYGEN SYSTEM (LOW PRESSURE ERRONEOUS INDICATION) - FUNCTIONAL TEST						Service ATA:35
	MOS			25-Aug-23				17-Nov-2025
	HRS	600 (+60/-60)		1160.7	1760.7	1820.7	228.9 (+60)	
	AFL			1249				
Disposition: AIRWORTHINESS		REF: AMM 35-00-01, AMM 35-00-03						
35HA3500106		DO THE FUNCTIONAL TEST OF THE CREW AND PASSENGER OXYGEN SYSTEM NOTE: ACCOMPLISHMENT OF THIS AMM TASK SATISFIES THE REQUIREMENTS OF BOTH INSPECTION TASK 35HA3500106 IN THIS SECTION AND TASK 35HA3500101 IN SECTION 05-60.						Service ATA:35
	MOS			25-Aug-23				17-Nov-2025
	HRS	600 (+60/-60)		1160.7	1760.7	1820.7	228.9 (+60)	
	AFL			1249				
		REF: AMM 35-00-01						
35HA3500107		DO THE LEAK TEST OF THE CREW AND PASSENGER OXYGEN SYSTEM NOTE: ACCOMPLISHMENT OF THIS AMM TASK SATISFIES THE REQUIREMENTS OF BOTH INSPECTION TASK 35HA3500107 IN THIS SECTION AND TASK 35HA3500102 IN SECTION 05-60.						Service ATA:35
	MOS			25-Aug-23				17-Nov-2025
	HRS	600 (+60/-60)		1160.7	1760.7	1820.7	228.9 (+60)	
	AFL			1249				
		REF: AMM 35-00-02						
36HA3600101		OPERATIONAL TEST - MANIFOLD TEMPERATURE SENSOR						Service ATA:36
	MOS			25-Aug-23				17-Nov-2025
	HRS	600 (+60/-60)		1160.7	1760.7	1820.7	228.9 (+60)	
	AFL			1249				
Disposition: AIRWORTHINESS		REF: AMM 36-00-01						

?-Insufficient Information S -Suppressed Requirement \* -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



## Due List Report

Model: HONDAJET HA-420 ELITE Serial: 42000138 RegNo: N542MP HRS: 1531.8  
AFL: 1644 As Of: 15-Sep-2024 Operator: CLAY LACY AVIATION, INC.

Report Date: 20-Sep-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est. Due
51HA5180101		ELECTRICAL POWER BONDING AND GROUNDING PROCEDURE - FUNCTIONAL CHECK						Service ATA:51
	MOS				25-Aug-23			17-Nov-2025
	HRS	600 (+60/-60)		1160.7	1760.7	1820.7	228.9 (+60)	
	AFL			1249				
Disposition: AIRWORTHINESS		REF: AMM 51-81-10						
52HA0500111		VENT PATH FROM THE FORWARD BAGGAGE AREA TO THE NOSE LANDING GEAR BAY AND RADOME AND UNDER FLOOR AREA - VISUAL INSPECTION						Service ATA:52
	MOS				25-Aug-23			17-Nov-2025
	HRS	600		1160.7	1760.7		228.9	
	AFL			1249				
Disposition: AIRWORTHINESS		REF: ALIM INTRO						
52HA0500113		MAIN ENTRY DOOR LOWER HINGE PIN - DETAILED INSPECTION						Service ATA:52
	MOS				25-Aug-23			17-Nov-2025
	HRS	600		1160.7	1760.7		228.9	
	AFL			1249				
Disposition: AIRWORTHINESS		REF: AMM 52-11-20						
52HA5210103		MAIN ENTRY DOOR (MED) WARNING SYSTEM; INCLUDING MED SWITCHES - FUNCTIONAL TEST						Service ATA:52
	MOS				25-Aug-23			17-Nov-2025
	HRS	600 (+60/-60)		1160.7	1760.7	1820.7	228.9 (+60)	
	AFL			1249				
Disposition: AIRWORTHINESS		REF: AMM 52-10-03						
74-00-00-440-801		NO. 2 ENGINE - REPLACE 4 OCLOCK IGNITER PLUG						Service ATA:74
PN:PN	MOS				25-Aug-23			17-Nov-2025
SN:UNKNOWN	HRS	600		1105.9	(1705.9)1760.7		228.9	
	ENC			1128				
		REF:						
74-00-00-440-801		NO. 2 ENGINE - REPLACE 8 OCLOCK IGNITER PLUG						Service ATA:74
PN:PN	MOS				25-Aug-23			17-Nov-2025
SN:UNKNOWN	HRS	600		1105.9	(1705.9)1760.7		228.9	
	ENC			1128				
		REF:						
12CA1211121		TAKE / TEST A HYDRAULIC FLUID SAMPLE MIL-PRF-87257						Service ATA:12
	MOS				25-Aug-23			24-Jan-2026
	HRS	600 (+60/-60)	Adj:37	1160.7	1797.7	1857.7	265.9 (+60)	
	AFL			1249				
		REF: AMM 12-11-12						

?-Insufficient Information S -Suppressed Requirement \* -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



## Due List Report

Model: HONDAJET HA-420 ELITE Serial: 42000138 RegNo: N542MP HRS: 1531.8  
AFL: 1644 As Of: 15-Sep-2024 Operator: CLAY LACY AVIATION, INC.

Report Date: 20-Sep-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est. Due
29CA2911171		REPLACE HYDRAULIC FILTERS P/N 0711311-861, ACA902F815						Service ATA:29
	MOS			25-Aug-23				24-Jan-2026
	HRS	600 (+60/-60)	Adj:37	1160.7	1797.7	1857.7	265.9 (+60)	
	AFL			1249				
REF: AMM 29-11-17								
29HA0500105		DO A VISUAL INSPECTION OF ALL HYDRAULIC PLUMBING.						Service ATA:29
	MOS			30-Aug-21				24-Jan-2026
	HRS	1200 (+60/-60)		597.7	1797.7	1857.7	265.9 (+60)	
	AFL			597				
REF: ALIM INTRO								
30HA0500101		DO A VISUAL INSPECTION OF ALL ICE AND RAIN PROTECTION TUBING, COUPLINGS, SENSORS, AND CLAMPS.						Service ATA:30
	MOS			30-Aug-21				24-Jan-2026
	HRS	1200 (+60/-60)		597.7	1797.7	1857.7	265.9 (+60)	
	AFL			597				
REF: ALIM INTRO								
32HA0500107		DO A VISUAL INSPECTION OF THE MASTER CYLINDERS.						Service ATA:32
	MOS			30-Aug-21				24-Jan-2026
	HRS	1200 (+60/-60)		597.7	1797.7	1857.7	265.9 (+60)	
	AFL			597				
REF: ALIM INTRO								
34HA0500103		DO THE VISUAL INSPECTION OF THE ANTENNA, ANTENNA MOUNTS AND CABLES.						Service ATA:34
	MOS			30-Aug-21				24-Jan-2026
	HRS	1200 (+60/-60)		597.7	1797.7	1857.7	265.9 (+60)	
	AFL			597				
REF: ALIM INTRO								
35HA0500105		DO A VISUAL INSPECTION OF THE CABIN OXYGEN SYSTEM.						Service ATA:35
	MOS			30-Aug-21				24-Jan-2026
	HRS	1200 (+60/-60)		597.7	1797.7	1857.7	265.9 (+60)	
	AFL			597				
REF: ALIM INTRO								
36HA0500104		DO THE INSPECTION OF THE CABIN CHECK VALVES.						Service ATA:36
	MOS			30-Aug-21				24-Jan-2026
	HRS	1200 (+60/-60)		597.7	1797.7	1857.7	265.9 (+60)	
	AFL			597				
REF: AMM 36-00-01								

?-Insufficient Information S -Suppressed Requirement \* -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



## Due List Report

Model: HONDAJET HA-420 ELITE Serial: 42000138 RegNo: N542MP HRS: 1531.8  
 AFL: 1644 As Of: 15-Sep-2024 Operator: CLAY LACY AVIATION, INC.

Report Date: 20-Sep-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est. Due	
53HA0500109		DO A VISUAL INSPECTION OF THE FUSELAGE BILGE DRAINS.							Service ATA:53
	MOS			30-Aug-21				24-Jan-2026	
	HRS	1200 (+60/-60)		597.7	1797.7	1857.7	265.9 (+60)		
	AFL			597					
		REF: ALIM INTRO							
05CA0520001		600 HOUR SCHEDULED INSPECTIONS (CHECKS)							Package ATA:05
	MOS			25-Aug-23				28-Jan-2026	
	HRS	600 (+60/-60)	Adj:39.3	1160.7	1800	1860	268.2 (+60)		
	AFL			1249					
		REF: ALIM 05-20-00							
72-00-00-200-802		NO. 1 ENGINE - BORESCOPE INSPECTION OF ENGINE							Service ATA:72
	MOS			25-Aug-23				20-Feb-2026	
	HRS	600		1157.5	(1757.5)1812.3		280.5		
	ENC			1218					
		REF:							
72-00-00-200-802		NO. 2 ENGINE - BORESCOPE INSPECTION OF ENGINE							Service ATA:72
	MOS			25-Aug-23				20-Feb-2026	
	HRS	600		1157.5	(1757.5)1812.3		280.5		
	ENC			1218					
		REF:							
72-00-00-200-804		NO. 1 ENGINE - DETAILED INSPECTION INNER SURFACE OF FAN CASE							Service ATA:72
	MOS			25-Aug-23				20-Feb-2026	
	HRS	600		1157.5	(1757.5)1812.3		280.5		
	ENC			1218					
		REF:							
Disposition: MANDATORY									
72-00-00-200-804		NO. 2 ENGINE - DETAILED INSPECTION INNER SURFACE OF FAN CASE							Service ATA:72
	MOS			25-Aug-23				20-Feb-2026	
	HRS	600		1157.5	(1757.5)1812.3		280.5		
	ENC			1218					
		REF:							
Disposition: MANDATORY									
72-00-00-200-805		NO. 1 ENGINE - DETAILED INSPECTION OF EXPOSED ENGINE							Service ATA:72
	MOS			25-Aug-23				20-Feb-2026	
	HRS	600		1157.5	(1757.5)1812.3		280.5		
	ENC			1218					
		REF:							

?-Insufficient Information S -Suppressed Requirement \* -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



## Due List Report

Model: HONDAJET HA-420 ELITE Serial: 42000138 RegNo: N542MP HRS: 1531.8  
AFL: 1644 As Of: 15-Sep-2024 Operator: CLAY LACY AVIATION, INC.

Report Date: 20-Sep-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est. Due	
72-00-00-200-805		NO. 2 ENGINE - DETAILED INSPECTION OF EXPOSED ENGINE							Service ATA:72
	MOS			25-Aug-23				20-Feb-2026	
	HRS	600		1157.5	(1757.5)1812.3		280.5		
	ENC			1218					
		REF:							
72-00-00-200-806		NO. 1 ENGINE - DETAILED INSPECTION OF THE CORE INNER DUCT ASSEMBLY							Service ATA:72
	MOS			25-Aug-23				20-Feb-2026	
	HRS	600		1157.5	(1757.5)1812.3		280.5		
	ENC			1218					
		REF:							
72-00-00-200-806		NO. 2 ENGINE - DETAILED INSPECTION OF THE CORE INNER DUCT ASSEMBLY							Service ATA:72
	MOS			25-Aug-23				20-Feb-2026	
	HRS	600		1157.5	(1757.5)1812.3		280.5		
	ENC			1218					
		REF:							
73-00-00-200-801		NO. 1 ENGINE - DETAILED INSPECTION MECHANICAL FUEL SHUTOFF SYSTEM (MFSS)							Service ATA:73
	MOS			25-Aug-23				20-Feb-2026	
	HRS	600		1157.5	(1757.5)1812.3		280.5		
	ENC			1218					
		REF:							
Disposition: MANDATORY									
		REF:							
73-00-00-200-801		NO. 2 ENGINE - DETAILED INSPECTION MECHANICAL FUEL SHUTOFF SYSTEM (MFSS)							Service ATA:73
	MOS			25-Aug-23				20-Feb-2026	
	HRS	600		1157.5	(1757.5)1812.3		280.5		
	ENC			1218					
		REF:							
Disposition: MANDATORY									
		REF:							
73-00-00-610-801		NO. 1 ENGINE - REPLACE FUEL FILTER							Service ATA:73
	MOS			25-Aug-23				20-Feb-2026	
	HRS	600		1157.5	(1757.5)1812.3		280.5		
	ENC			1218					
		REF:							
73-00-00-610-801		NO. 2 ENGINE - REPLACE FUEL FILTER							Service ATA:73
	MOS			25-Aug-23				20-Feb-2026	
	HRS	600		1157.5	(1757.5)1812.3		280.5		
	ENC			1218					
		REF:							

?-Insufficient Information S -Suppressed Requirement \* -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



## Due List Report

Model: HONDAJET HA-420 ELITE Serial: 42000138 RegNo: N542MP HRS: 1531.8  
AFL: 1644 As Of: 15-Sep-2024 Operator: CLAY LACY AVIATION, INC.

Report Date: 20-Sep-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est. Due	
74-00-00-440-801		NO. 1 ENGINE - REPLACE 4 OCLOCK IGNITER PLUG						Service	ATA:74
PN:31111-Q0A-0000	MOS				27-Nov-23			20-Feb-2026	
SN:UNLBB828	HRS	600		1157.5	(1757.5)1812.3		280.5		
	ENC			1218					
REF:									
74-00-00-440-801		NO. 1 ENGINE - REPLACE 8 OCLOCK IGNITER PLUG						Service	ATA:74
PN:31111-Q0A-0000	MOS				27-Nov-23			20-Feb-2026	
SN:UNLBB827	HRS	600		1157.5	(1757.5)1812.3		280.5		
	ENC			1218					
REF:									
77-00-00-750-801		NO. 1 ENGINE - TEST ENGINE VIBRATION DETECTION SYSTEM						Service	ATA:77
	MOS				25-Aug-23			20-Feb-2026	
	HRS	600		1157.5	(1757.5)1812.3		280.5		
	ENC			1218					
REF:									
77-00-00-750-801		NO. 2 ENGINE - TEST ENGINE VIBRATION DETECTION SYSTEM						Service	ATA:77
	MOS				25-Aug-23			20-Feb-2026	
	HRS	600		1157.5	(1757.5)1812.3		280.5		
	ENC			1218					
REF:									
79-00-00-200-801		NO. 1 ENGINE - DETAILED INSPECTION CHIP DETECTOR						Service	ATA:79
	MOS				25-Aug-23			20-Feb-2026	
	HRS	600		1157.5	(1757.5)1812.3		280.5		
	ENC			1218					
REF:									
79-00-00-200-801		NO. 2 ENGINE - DETAILED INSPECTION CHIP DETECTOR						Service	ATA:79
	MOS				25-Aug-23			20-Feb-2026	
	HRS	600		1157.5	(1757.5)1812.3		280.5		
	ENC			1218					
REF:									
79-00-00-610-802		NO. 1 ENGINE - REPLACE ENGINE OIL						Service	ATA:79
	MOS				25-Aug-23			20-Feb-2026	
	HRS	600		1157.5	(1757.5)1812.3		280.5		
	ENC			1218					
REF: GENERIC NO REF									



## Due List Report

Model: HONDAJET HA-420 ELITE Serial: 42000138 RegNo: N542MP HRS: 1531.8  
 AFL: 1644 As Of: 15-Sep-2024 Operator: CLAY LACY AVIATION, INC.

Report Date: 20-Sep-2024

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est. Due	
79-00-00-610-802		NO. 2 ENGINE - REPLACE ENGINE OIL						Service	ATA:79
	MOS			25-Aug-23				20-Feb-2026	
	HRS	600		1157.5	(1757.5)1812.3		280.5		
	ENC			1218					
REF: GENERIC NO REF									
79-00-00-610-803		NO. 1 ENGINE - REPLACE ENGINE OIL FILTER						Service	ATA:79
	MOS			25-Aug-23				20-Feb-2026	
	HRS	600		1157.5	(1757.5)1812.3		280.5		
	ENC			1218					
REF: GENERIC NO REF									
79-00-00-610-803		NO. 2 ENGINE - REPLACE ENGINE OIL FILTER						Service	ATA:79
	MOS			25-Aug-23				20-Feb-2026	
	HRS	600		1157.5	(1757.5)1812.3		280.5		
	ENC			1218					
REF: GENERIC NO REF									
25CA2563062		ELT BATTERY (REPLACE) P/N 0141823						Component	ATA:25
PN:PN-UNKNOWN	MOS	72		30-Aug-21	28-Feb-26		526 d	28-Feb-2026	
SN:UNKNOWN	HRS			597.7					
	AFL			597					
Disposition: DISCARD		REF: CMM 25-63-08							